

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/05/2023

User ID : JeongCH

Section A - Accident Details	
Registration Number	SMB1323Y
Case Reference Number	BUS/05/23/7009
Registration Date	3/25/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Jonaydi Bin Basri
Type of Accident	Head to Rear
Accident Date and Time	5/6/2023 9:39 PM
Accident Reported Date and Time	5/15/2023 2:03 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB1323Y - Right front body dented SLA6133M (TP) - INSURED WITH AIG
Prepared Date and Time	5/23/2023 11:07 AM
Chassis Number	WMAA22ZZXD7001779
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$75.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,656.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	23/05/2023 11:11 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Taufikh 97495749
WP 23/5/23 @230PM
Resurvey after repair
2 days
taufikh@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/05/2023

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$795.00				530	
Total Labour				\$795.00					
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$786.00				616	
Total Spray Painting & Panel Beating				\$786.00					
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010154	Body	F01001-CW263	FLAP,FRONT:FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	XR
6010064	Body	F01001-CW274	BUMPER:REAR,CENTR E,FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	XR
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT ,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	XR
			SMRT STICKERS	1.00	\$75.00	0.00	\$75.00	Replace	NEC ✓
Total					\$4,787.30		\$75.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									