

ASS. REC. BY: TajjREF: 05/INC 23005219/Typ 3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: **FBT 7990S**

Policy No. \_\_\_\_\_


Claims No. **MT/1224031-002**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$55K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wp

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLR4849FYr Regn: 2017 AugType: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MitsubishiColour: WhiteSp. Reading: 67090

Eng/No: \_\_\_\_\_

C/No: MMB5TA 13AMH0043LYGen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55 R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Aoteli

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 21/5/2023Survey held at AutobacsDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 23/5/23

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                  |
|-------------|---|
| 7/6/23      | Lump Sum \$1600 confirmed by email (red 2546.60, 61%) |
|             |   |
|             |   |
|             |   |
|             |   |
|             |   |
|             |   |
|             |   |

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) 7/6/23-typist

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: TPLump Sum / FBT: (\$) \$1600



# **AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444

Co. Reg No. : 201500047H GST No. : 201500047H

Email : st.sim@autobacs.com.sg

|                         |                           |                |                     |
|-------------------------|---------------------------|----------------|---------------------|
| TO                      | : NTUC (FBT7990S)         | DATE           | : 22-May-23         |
| ATTENTION               | : MOTOR CLAIMS DEPARTMENT | JOB TYPE       | : T/P CLAIMS        |
| <b>OWNER PARTICULAR</b> |                           |                |                     |
| OWNER ID                | : SXXXX400E               | P -            | _____               |
|                         |                           | S -            | _____               |
|                         |                           | L -            | _____               |
| <b>VEHICLE DETAILS</b>  |                           | TOTAL :        | _____               |
| VEHICLE NO.             | : SLR4849E                | L/S -20% :     | _____               |
| MODEL / MAKE            | : MIT ATTRAGE             | SUB TOTAL :    | _____               |
| CHASSIS NO.             | : MMBSTA13AHH004314       |                | _____               |
| <b>ACCIDENT DETAIL</b>  |                           |                |                     |
| DATE                    | : 21-May-23               |                |                     |
| TIME                    | : 14:20HRS                | CONTACT PERSON | : MR. SIM 9844 0974 |

QUOTATION SUMMARY PAGE 01

## **CLAIMS DETAIL : PARTS LIST**

| S/N             | DESCRIPTION                       | QTY | UNIT NETT PRICE | TOTAL NETT PRICE     |
|-----------------|-----------------------------------|-----|-----------------|----------------------|
| 1               | REAR BOOT LID LOGO EMBLEM         | 1   | \$ 41.00        | \$ <i>net</i> 41.00  |
| 2               | REAR BOOT LID ATTRAGE EMBLEM      | 1   | \$ 35.00        | \$ <i>net</i> 35.00  |
| 3               | REAR BOOT LID LOCK                | 1   | \$ 206.00       | \$ <i>net</i> 206.00 |
| 4               | REAR BOOT LID WEATHER STRIP       | 1   | \$ 148.00       | \$ <i>net</i> 148.00 |
| 5               | REAR BUMPER                       | 1   | \$ 708.00       | \$ <i>net</i> 708.00 |
| 6               | REAR BUMPER SIDE RETAINER LH / RH | 2   | \$ 26.00        | \$ <i>x</i> 52.00    |
| 7               | REAR BUMPER REFLECTOR RH          | 1   | \$ 20.00        | \$ <i>x</i> 20.00    |
| 8               | REAR END PANEL                    | 1   | \$ 402.00       | \$ <i>?</i> 402.00   |
| 9               | REAR END PANEL INNER TOP GARNISH  | 1   | \$ 62.00        | \$ <i>?</i> 62.00    |
| TOTAL PRICE     |                                   |     |                 | \$ 1,674.00          |
| LESS -10%       |                                   |     |                 | \$ (167.40)          |
| SUB TOTAL PRICE |                                   |     |                 | \$ 1,506.60          |

## **CLAIMS DETAIL : PARTS LIST**

| S/N   | DESCRIPTION                                | QTY | UNIT S/NETT | TOTAL S/NETT             |
|-------|--|-----|-------------|--------------------------|
| 1     | REAR BUMPER CLIPS SET                      | 1   | \$ 60.00    | \$ <i>30 net</i> 60.00   |
| 2     | REAR BUMPER REVERSE SENSOR SET             | 1   | \$ 280.00   | \$ <i>200 net</i> 280.00 |
| 3     | REAR END PANEL INNER TOP GARNISH CLIPS SET | 1   | \$ 50.00    | \$ <i>x</i> 50.00        |
| 4     | REAR END PANEL SEALANT                     | 1   | \$ 80.00    | \$ <i>x</i> 80.00        |
| TOTAL |  |     |             | \$ 470.00                |

## CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

|   |           |                       |  |
|---|-----------|-----------------------|--|
| TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION                                 | \$ 800.00 | 500<br><del>400</del> |  |
| TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA                                | \$ 600.00 | 400                   |  |
| TO APPLY ANTI-RUST & TUFF KOTE  | \$ 120.00 | x                     |  |
| TO PERFORM LIGHTING & WIRING CHECK  | \$ 150.00 | x                     |  |
| TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING                            | \$ 150.00 | 30                    |  |
| TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR | \$ 250.00 | 60.                   |  |
| TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION   | \$ 100.00 | x                     |  |

TOTAL \$ 2,170.00

## ESTIMATE REPORT

|                   |   |             |
|-------------------|---|-------------|
| TOTAL PARTS COST  | : | \$ 1,976.60 |
| TOTAL LABOUR COST | : | \$ 2,170.00 |
| TOTAL REPAIR COST | : | \$ 4,146.60 |

## APPROVED DETAILS

NO. OF REPAIR DAYS

3-4

DAYS

REPAIR UNDER

PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY

23/5/23

SURVEYED BY / FROM

Taufik LKH

CONTACT NUMBER

97495749 / 62503561

EMAIL ADDRESS

taufik@lkhauto.com

LKH Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 400E

Vehicle Details

Vehicle No.: SLR4849E  
Vehicle to be Exported: No  
Intended Deregistration Date: 22 May 2023  
Vehicle Make: MITSUBISHI  
Vehicle Model: ATTRAGE 1.2 CVT  
Primary Colour: White  
Manufacturing Year: 2016  
Engine No.: 3A92UDS0612  
Chassis No.: MMBSTA13AHH004314  
Maximum Power Output: 57.0 kW (76 bhp)  
Open Market Value: \$13,450.00  
Original Registration Date: 17 Aug 2017  
First Registration Date: 17 Aug 2017  
Transfer Count: 2  
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 16 Aug 2027  
PARF Rebate Amount: \$3,500.00

Intended COE Rebate Details

COE Expiry Date: 16 Aug 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$49,430.00  
COE Rebate Amount: \$20,928.00  
Total Rebate Amount: \$24,428.00

The information contained herein is correct as at 22 May 2023

OK

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |  |
|---------------------------------|--|
| Date of Submission              | 22/05/2023 15:08 (SGT)   |
| Reported by                     | Both Policyholder and Actual Driver                              |
| Date of Accident                | 21/05/2023 14:20 (SGT)   |
| Exact Location of Accident      | Singapore  |
| Additional Location Information | Exit towards PIE Tuas, around Bedok North & Bedok Reservoir Road |
| Country/State of Loss           | Singapore  |

## DETAILS OF OWN VEHICLE

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SLR4849E |
|-----------------------------|----------|

### INSURED/POLICYHOLDER

|                          |                         |
|--------------------------|-------------------------|
| Is company?              | No                      |
| Name Of Registered Owner | Lim Yi Chan, Priscillin |
| NRIC No                  | SXXXX400E               |
| Email Address            | priscillin@gmail.com    |
| Mobile Phone No          | (Phone) +65-90677188    |
| Alternative Phone No     | -                       |

### VEHICLE PARTICULARS

|  |                           |
|--|---------------------------|
| Manufacturer   | Mitsubishi                |
| Model  | Attrage                   |
| Variant  | -                         |
| Exact purpose for which vehicle was being used at time of accident           | Private hire              |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category   | Private car               |
| Transmission   | Auto                      |
| CC   | 1200                      |

### INSURANCE COMPANY

|                                   |                                      |
|-----------------------------------|--------------------------------------|
| Name of Insurance Company         | MSIG Insurance (Singapore) Pte. Ltd. |
| Policy Number / Cover Note Number | A300529376QMX                        |

### DRIVER

|                |                         |
|----------------|-------------------------|
| Name of Driver | Lim Yi Chan, Priscillin |
| NRIC No        | SXXXX400E               |
| Date Of Birth  | 17/10/1985              |

Occupation  
Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

Indoor  
21/06/2012  
10 YEARS AND 11 MONTHS  
Female  
(Phone) +65-90677188  
-  
priscillin@gmail.com  
Blk 712, Bedok Reservoir Road, #11-3924  
-  
-  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Collided into Motorcyclist  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other vehicle or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?  
Translator's name  
Translator's ID  
Translator's phone number  
Translator's email  
Original language used in the statement

No  
2  
No  
-  
Yes  
1  
No  
-  
-  
-  
-  
-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Was notice of intended Prosecution given?  
If yes, against whom?

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

Please refer to the accident statement

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?

Yes  
No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver

FBT7990S  
-  
-  
-  
-  
Motorcycle  
-

From: **NOTICE**  
Estimate must be completed by the Policyholder and/or the Actual Driver.  
Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.  
The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.  
Any false reporting may be referred to the Traffic Police Department for investigation.

This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.  
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)



Sketch Plan




ODI (P)

To Ins


The accident happened on 21st May 2023 around 2.20pm, at the scene of exit towards PIE Turn. I heard a bump and a bike had bumped into my car's rear.

## Declaration

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date &amp; Time

  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)