

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196R GS1 Reg. No. 19-900/196-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL		Ref:	CS/AGI23005235/Aqp3e2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		I	Date:	19/06/2023	
			•	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SCY 9896E	Veh. Inspected		SLR 6974M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10022379/KR	Excess (\$)		0.00	
	Assign From	LEONG ENG MING	Assign Date		22/05/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA CHR	c.c		1196	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	NGX502009989	Colour		BLUE	
	Odometer	96921 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/60 R17	HABILEAD		6 mm	
	L/H Front Tyre	225/60 R17	HABILEAD		6 mm	
	R/H Rear Tyre	225/60 R17	HABILEAD		6 mm	
	L/H Rear Tyre	225/60 R17	HABILEAD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	18/05/2023	Inspection Date	;	22/05/2023	
	Survey held at	YSK AUTO WORKSHOP				
		1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: