

 Service Request Details

Claim	S3M04MQM
Reference	CS3/HSB23005280/Tnp3e2 
Loss Date	20 May 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	23 May 2023 9:18:37 AM
Request Date	24 May 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information	
Incident	SKU213L
Vehicle	
Registration #	
Make	TPVD
Model	Volvo
Service Address	
, , ,	
Primary Contact/Insured	

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Invoice



Surveyor/ Assessor expense



Upload Documents

Already Attached

NAME

DATE UPLOADED

NAME

TYPE

SUBTYPE

AUTHOR

DATE
UPLOADED [HSB-LKKInvoice-AC2303548.pdf.pdf](#)

Invoice

Surveyor/ Assessor
expenseLKK AUTO CONSULTANTS
PTE LTD (TP)

7 June 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2023
 SKU 213L-IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 June 2023
 EMAIL FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	30 May 2023
 EMAIL FR TP ON PRI DATE.msg.msg	Letters and Correspondence	Third Party	OH Vale	30 May 2023
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	24 May 2023
 TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	24 May 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 SURVEY LIST.msg.msg	Legal	Others	KUMAR Shailendra	24 May 2023
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	24 May 2023
 SJ0G235M001C-SHD6990L.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	23 May 2023