AUTHORIZE WORKSHOP PTE LTD

160, Sin Ming Drive, #03-19, Sin Ming Autocity, Sing apore 575722 Tel: 64560226 Fax: 64584500

Registration No: 201603203R

Not Nothern

ESTIMATE 24th May 2023 Date M/s **E** Rental 160 Sin Ming Drive Veh No SJA 9164C #03-19 Sin Ming AutoCity Make/Model Toyota Axio Singapore 575722 Chassis No NZE1416050484 Date of Acc : 23.05.23 Attn: TP Veh No : SJX 5284U

S/No	Qty	Description	Unit Price	Amount
		Materials	a. In	
1	1 pc	Rear Bumper 365.20	Br Ingen	1,485.95
2	1 pc	Rear Bumper Side Retainer RH	9	93.80
3	1 pc	Rear Lamp RH		452.00
4	1 pc	Rear Fender RH		965.90
5	1 pc	Rear Windscreen Moulding	nn	
6	1 pc	Rear Fender Inner Liner RH		5 cm 93.10
7	1 pc	Rear Door RH	7	799.70
8	1 pc	Rear Door Outer Handle RH		5 Ju 86.20
9	1 pc	Rear Door Window Outer Moulding RH		5 Su 121.30
10	1 set	Rear Door Black Sticker RH	,	65.80 G
11	1 pc	Rear Door Trim Board RH	0:1/1	5 Sn 578.20
12	1 pc	Rear Door Regulator Gear Assy RH 385	VISI M	529.30
13	1 pc	Rear Door Weatherstrip RH		5 h 198.80
14	2 pcs	Rear Door Hinges RH, Top & Lower		185.00
15	1 pc	Rear Door Center Checker RH		126.50
16	1 pc	Frt Door RH	,	822.80
17	1 set	Frt Door Black Sticker RH		s Mer 65.80
18	1 pc	Frt Door Window Outer Moulding RH		5 Pm 121.30
19	1 pc	Frt Door RH Mechanism Lock RH		456.90
20	2 pcs	Frt Door Hinge. Top & Lower RH	92.5	185.00
21	1 pc	Frt Door Center Checker RH	,	126.50
22	1 pc	Frt Door Regulator Gear Assy		590.90
23	1 pc	Side Rocker Panel RH		682.50
24	1 pc	Rear Shock Absorber RH		158.90
25	1 pc	Rear Hub Assy RH 645		5 M 784.00
26	1 pc	Rear Axle	137	\$ 1,636.60
				\$ 11,570.95
			Less 25% : .	2,892.74
			Parts Total :	\$ 8,678.21
		Special Nett	_	-
1	1 set	Rear Bumper Clips		5 Me 45.00
2	1 set	Rear Fender Liner Clips		35.00
3	1 set	Rear Door Visor RH	Ma	\$ 250.00
4	1 pc	Rear Sport Rim RH		450.00
5	1 pc	Windscreen Sealant		5 NN 50.00
6	1 pc	E Rental Door Sticker		5 ma 50.00
			_	\$ 880.00
		<u>Labour</u>		
1	To remove	& rearrange electrical wirings, check lightings		80.00
2	To remove	& replace upholstry, cushion seat & trim garnishes.		\$ 100.00
3	To remove,	, reinstal rear windscreen.		150.00
4	To remove	, transfer rear door components		\$ 120.00

Estimate - SJA 9164C

5	To remove, replace rear axle, suspension undercarriage parts.	\$ 450.00	2001
6	To reset wheel alignment	\$ 100.00	
7	To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$ 1,000.00	8001
8	Putty and respray painting on affected portions.	\$ 1,000.00	Control March
9	To remove & refit reverse sensor	\$ 100.00	501
10	Rust proofing on affected portions.	\$ 100.00	901
		\$ 3,200.00	-

Total Parts & Labour : \$ 12,758.21

for Authorize Workshop Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

> LKK Auto Consultants hence notify the Repairer of the following:
>
> To resurve: before er apray painting
> To display (lamage operits) during resurvey

- Parts price are subject to confirmation
- Third party survey a "Without Prejudice" basis
- No illegal mouthcation; is allowed.
- Supplementary item(s) must Lo resurveyed and is subject to final approval from Insurance Company

Acknowledge 1 by Repairer

Signature:

Date:



Toyota: Corolla / Sprinter 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-1°08'	-1°08'	-1°20' 0°10'
2°43'	2°43'	2°15' 3°45'
-0°05'	-0°05'	-0°06' 0°06'
11041	11041	10°40' 12°10'
10°33'	10°33'	9°20' 12°20'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

	Act	ual	Before	Specified Range
	-0°	6'	-0°16'	-1°20' 0°10'
	3°0	0'	3°00'	2°15' 3°45'
	0°C	3'	0°03'	-0°06' 0°06'
	110	26'	11°26'	10°40' 12°10'
	110	10'	11°10'	9°20' 12°20'

Front: Right

Front

Cross Camber Cross Caster Cross SAI Total Toe Cross Turn Diff.

Before	Specified Range
-0°53'	
-0°17'	
0°15'	
-0°02'	-0°11' 0°11'
	-0°53' -0°17' 0°15'

Rear: Left

Actual	Before	Specified Range
-1°37'	-1°37°	-2°15' -0°45'
0°12'	0°12'	0°00' 0°11'

Camber Toe

		Rear:	Right
Act	ıal	Before	Specified Range
-2°3	6'	-2°36'	-2°15' -0°45'
-0°1	6'	-0°16'	0°00' 0°11'

Rear

Cross Camber Total Toe Thrust Angle Axle Offset

Actual	Before	Specified Range
0°59'	1°00'	
-0°04'	-0°04'	0°00' 0°22'
0°14'	0°14'	
0mm	0mm	

For surveyor

SL'0M235N0007 / Lai Huat (Meng Kee) Motor Pte Ltd ENTRY DATE & TIME: 23/05/2023 17:17 (SGT) SUBMITTED BY: LHMK -3 VERSION: 1 (23/05/2023 17:17 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of mater al facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

23/05/2023 17:17 (SGT) **Actual Driver** 23/05/2023 13:20 (SGT) KPE, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SJA9164C

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No

Yes **E RENTAL** 53129868W

emautosolution@singne .com.sg (Phone) +65-64560226

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

CC

Transmission

Toyota

Axio

Private hire

No - Claiming third party

Private hire Auto

1600

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number Liberty Insurance Pte Ltd SD23V00037/VPZ/R05

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

GOH SOK HIONG ERIC S1609319Z 02/07/1963 Outdoor

Accident report SL0M235N0007

Date Of Driving Pass 15/09/1986 Driving experience 36 YEARS AND 8 MONTHS Gender Mobile Number (Phone) +65-97359360 Alt. Phone Number **Email Address** emautosolution@singnet com.sg Address BLK 422 SERANGOON CENTRAL #09-360 Address complement Postcode 550422 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Authorised driver Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Change/cross lane Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT Please refer to the sketch plan. ATTACHMENT(S) Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY

No

Vehicle Registration Number SJX5284U Vehicle Manufacturer Mercedes Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver HO YEE KEONG IAN NRIC No

S9106731E

Was there any video captured by Car Camera?

Contact Number	(Phone) +65-94355142
Address	•
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withit biding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability or the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 5. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon applic ition by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the entre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in his accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necestary investigations relating to the claims:
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external lover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party sen ice providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Furposes.

Policyholder's Signature / Date &

Witnessed by Reporting Centre Per (Name as in NRIC/ID card) 30H

Sketch Plan

Rimato Vetticle B skyped and collide (B) SJX 5284 U LOCATION: Inside KPE onto Vetticle A

Accident report SL0M235N0007

scribe Circumstance of the Accident	
Qu salatara	
(IN 23/5/2023	at about 1.20 pm & was travelling
along KPE toward &	At 98 smoothly when vetticle-B(SIX
5284 U doven Bu	1 PW HO YEE KEING LAN SHOW IN
31-01 011011 20	1 mm Ho YEE Keong, lan skipped and
Colliaga onle the 118	ght partion of my verticle - SJA 9164 c.
	·
MINCK OF 27 7 278 4	U (Mr Ho) apologized and admitted it
mas ms that and a	wanted to do a private - sittlement.
my Marishab Brioles	6 him \$1,400 - for repair - \$240 - for
loss of use. At lost	he refuse to pay and solved me to
Claim from his Insu	wane; glodge this riport for 3rd
party chain age	rot SJX 5284 4 for my dampes &
1 0	
PCS 62 ,	
Domaki: 3rd na	ty choin. at!
Venny Die be.	J Clark Pro
	EM SOLUTION PTE LTD
	160 Sili Mina Drive
	#03-18/19 llin Ming Autocity
	#03-18/19 lin Ming Autocity Singa pore 575722 Tel: 6456 02 16 Fax: 6458 4500 Email: emautosa utlan@singnet.com.sg

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is of the policyholder) / Date & Time

Vitnessed by Reporting Centre Personnel
(Name as In NRICAD card) 30 H J17







> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Business	
Owner ID: Vehicle Details	868W	
Vehicle No.:	SJA9164C	
Vehicle to be Exported:	No	
Intended Deregistration Date:	25 May 2023	
Vehicle Make:	TOYOTA	
Vehicle Model:	COROLLA AXIO 1.5X A	
Primary Colour:	Beige	
Manufacturing Year:	2007	
Engine No.:	1NZC739269	
Chassis No.:	NZE1416050484	
Maximum Power Output:	81.0 kW (108 bhp)	
Open Market Value:	\$11,758.00	
Original Registration Date:	26 Dec 2007	
First Registration Date:	26 Dec 2007	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$12,934.00	
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	-	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	30 Nov 2027	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
PQP Paid:	\$41,994.00	
COE Rebate Amount:	\$18,955.00	
Total Rebate Amount:	\$18,955.00	

The information contained herein is correct as at 24 May 2023 $\,$