

ASS REC. BY: John

REF:

03/FCI 2300 5295/Rgp3

682A

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SNH 1967X

at Workshop m/s PERFORMANCE

of ALEXANDRA 27

Insured:

FCI²

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

183k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Remove Limit - 47K

Veh No:

SNH 1967X

Yr Regn: 2022 / OCT

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W X1SDRIVE 181 HLXL c.c 1499

Colour

RED

A/C: Insured / Std / NI / NA

Sp. Reading

09195

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 32AA0 805 V22662

Gen. Cond: Good (F) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225 / 50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HANKOOK

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/05/23

D.O.I.

24/05/23

Survey held at

PERFORMANCE

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S Fnt

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

IN Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

3159 Sime Darby Performance Centre
Singapore 159941
Fax. 64747770
No illegal modification(s) is allowed
Supplier's name must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: 20020081 - X

Date:



GST REG. NO : M2

23 MAY 2023

ESTIMATE

Estimate No. : b1 66091
Date Estimated : 23/05/2023
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Wee Siming Sunny
93A Telok Blangah Street 31
#24-159

Singapore 101093

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNH1967X	WBA32AA0805V22662	03/10/2022	X1 sDrive18i	18

DESCRIPTION

To remove and make good front bumper

850 1,700.00

To respray front bumper

986 1,038.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

168 171.00

To check electrical wiring system and lighting

168 171.00

Sundries.

? 150.00

Total Labour 1: 3,242.00

DESCRIPTION

LH TAKE UP GRILLE TRIM (PDC BASIS/X

QTY	PRIC	VALUE
1	83.10	83.10

Total Parts : 83.10

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 24/05/23 @ 1215 Excess S\$ _____
Surveyor's Name Rasm Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

SURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

Working Days Recommend 3 days

Labour 1	:	3,242.00
Parts	:	83.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	266.01
Grand Total	:	3,591.11



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	682A
Vehicle Details	
Vehicle No.:	SNH1967X
Vehicle to be Exported:	No
Intended Deregistration Date:	24 May 2023
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE 18I LED HL XLINE
Primary Colour:	Orange
Manufacturing Year:	2022
Engine No.:	34686742B38A15F
Chassis No.:	WBA32AA0805V22662
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$37,122.00
Original Registration Date:	03 Oct 2022
First Registration Date:	03 Oct 2022
Transfer Count:	1
Actual ARF Paid:	\$43,971.00
PARF Eligibility Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Oct 2032
PARF Rebate Amount:	\$32,978.00
Intended COE Rebate Details	
COE Expiry Date:	02 Oct 2032
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$114,001.00
COE Rebate Amount:	\$102,911.00
Total Rebate Amount:	\$135,889.00

The information contained herein is correct as at 24 May 2023

OK

BMW X1 sDrive18i xLine


\$181,000 Instalment \$1,563/mth

CONSIGNMENT

 Apply for 2.28% loan

 Shortlist

 Loan Calculator



Overview Financial Photo Research

Depreciation	 \$16,990 / year
Reg. Date	24-Aug-2022 (9yrs 2mths 29days COE left)
Manufactured	 2022
Mileage	15,100 km
Transmission	Auto
Engine Cap	1,499 cc
Road Tax	 \$684 / year
Power	100.0 kW (134 bhp)
Curb Weight	 1,435 kg
COE	 \$114,001
OMV	 \$39,563
ARF	 \$47,389
Dereg Value	 \$122,964 as of today
No. of Owners	 1

Type of Veh 