

ASS REC. BY: Amu

REF:

CS/EQ/123005296/R9P3

3664

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 533 2266R

at Workshop m/s Volkswagen

of 247, Alexander Rd

Insured: EQ1

Policy No.

Chassis No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

4pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 139K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

REPAIR LIMIT - 38K

Rasul finalised final fig \$3245.58, 3 days. (Red \$5961.54, 65%)

Veh No:

533 2266R

Yr Regn: 2022 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen T-CROSS R-LINEc 999

Colour: ORANGE

A/C: Insured / Std / NI / NA

Sp. Reading: 5216

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WUW22C1ZN 468 7744

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 21/05/23

D.O.I. 29/05/23

Survey held at: Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1) 04/07 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 3245.58)

TOTAL

SWAGEN CENTRE SINGAPORE

axandra Road
pore 159934
Reg. No.: 199101494Z
r No.: M200985052



SKODA

Commercial Vehicles

29 May 2023 @ 4:00 pm
(LKK)

Quotation
Non binding - Preview

Page 1/2

Company
EQ INSURANCE COMPANY LIMITED
5 Maxwell Road, #17-00
Tower Block, MND Complex
Singapore 069110

Customer Details:
Mr
LIEW
SENG LEE
2 JALAN TAMAN
#07-09
SINGAPORE 329023

Document no.
Document date 23-05-2023
Customer no. 5211043754
Customer GST-ID 197800490N
Dealer 30001
Job order number 2023013850/ 1
Job order date 23-05-2023
Service Advisor Hui Wen Oh

License plate	Model code	First registration	VIN	Model	Mileage
SJJ2266R	C113KZR1	15-11-2022	WVGZZZC1ZNY087744	T-CROSS 1.0 Life G 085 TSID7F	5,000

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	X 280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
2GM807421 GRU	Cover For Bumper Primed	1	pcs.	1,368.47	#6	1,368.47	1,477.95
	REAR BUMPER (UPPER) repair						
2GM919397 GRU	Sensor Bracket Primed X	1	pcs.	15.35	#6	15.35	16.58
2GM919398 GRU	Sensor Bracket Primed X	1	pcs.	15.35	#6	15.35	16.58
2GM919491	Sensor Bracket X	1	pcs.	13.46	#6	13.46	14.54
2GM919491A	Sensor Bracket X	2	pcs.	13.46	#6	26.92	29.07
2GM919492	Sensor Bracket X	1	pcs.	13.46	#6	13.46	14.54
D 180KU2A1	2k-Plastic Adhesive X	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic X	1	pcs.	74.37	#6	74.37	80.32
2GM807521B GRU	Spoiler Primed	1	pcs.	428.99	#6	428.99	463.31
	REAR BUMPER (CTR) 3x repair						
2GM807568A 9B9	Rear Diffusor Satin Black	1	pcs.	325.58	#6	325.58	351.63
	REAR BUMPER (LOWER) 3x cut						
2GM807305	Bumper Bracket	1	pcs.	773.26	#6	773.26	835.12
	REINFORCEMENT 3x						
2GM807251C	Foam Insert X	1	pcs.	117.86	#6	117.86	127.29
2GM807863A	Attachment Strip	1	pcs.	71.65	#6	71.65	77.38
	BUMPER CTR BRACKET 3x						
2GM807393P	Guide Piece	1	pcs.	49.44	#6	49.44	53.40
	LHR BUMPER BRACKET (UPPER) 3x						
2GM807394P	Guide Piece	1	pcs.	49.44	#6	49.44	53.40
	RHR BUMPER BRACKET (UPPER) 3x						
2GM807393M	Guide Piece	1	pcs.	49.44	#6	49.44	53.40
	LHR BUMPER BRACKET (SIDE) 3x						
2GM807394M	Guide Piece	1	pcs.	49.44	#6	49.44	53.40
	RHR BUMPER BRACKET (SIDE) 3x						
	LABOUR	3	pcs.	840.00	#6	840.00	2,721.60
	SPRAY PAINT	3	pcs.	800.00	#6	800.00	2,592.00
	DESCRIPTION: ALLIANZ ARF VS EQ						
	DIRECT						
	DOA: 21/05/2023						
	TP VEH NO: GBM2299A						
	SURVEY BY:						

(bumper)

Quotation valid till 30-05-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	8,447.12	8%	736.57	9,207.12	9,943.69
Total	760.00	8,447.12		736.57	9,207.12	9,943.69

VOLKSWAGEN CENTRE SINGAPORE

Andra Road
ore 159934
g. No.: 199101494Z
No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page 2/2

Document no.
Document date 23-05-2023
Customer no. 5211043754
Customer GST-ID 197800490N
Dealer 30001
Job order number 2023013850/ 1
Job order date 23-05-2023
Service Advisor Hui Wen Oh

Company
EQ INSURANCE COMPANY LIMITED
5 Maxwell Road, #17-00
Tower Block, MND Complex
Singapore 069110

Customer Details:
Mr
LIEW
SENG LEE
2 JALAN TAMAN
#07-09
SINGAPORE 329023

License plate	Model code	First registration	VIN	Model	Mileage
SJJ2266R	C113KZR1	15-11-2022	WVGZZZC1ZNY087744	T-CROSS 1.0 Life G 085 TSID7F	5,000

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Revised
Hp 90010068
3 days
29/05/23 @ 1600
Revised after repair
new spoiler photo

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	366G
Vehicle Details	
Vehicle No.:	SJJ2266R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2023
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	T-CROSS R-LINE
Primary Colour:	Orange
Manufacturing Year:	2022
Engine No.:	DKJ125308
Chassis No.:	WVGZZZC1ZNY087744
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$22,380.00
Original Registration Date:	15 Nov 2022
First Registration Date:	15 Nov 2022
Transfer Count:	0
Actual ARF Paid:	\$23,332.00
PARF Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Nov 2032
PARF Rebate Amount:	\$17,499.00
Unexpired COE Vehicle Details	
COE Expiry Date:	14 Nov 2032
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$87,235.00
COE Rebate Amount:	\$82,532.00
Total Rebate Amount:	\$100,031.00

The information contained herein is correct as at 29 May 2023

OK

Volkswagen T-Cross 1.0A TSI R-Line

\$138,000 Instalment \$1,191/mth

PREMIUM AD

Apply for 2.28% loan

Shortlist

Loan Calculator



Overview Financial Photo Research

Depreciation	\$13,490 / year
Reg. Date	07-Oct-2022 (9yrs 4mths 6days COE left)
Manufactured	2022
Mileage	10,500 km
Transmission	Auto
Engine Cap	999 cc
Road Tax	\$392 / year
Power	85.0 kW (113 bhp) View specs of the Volkswagen T-Cross (2020)
Curb Weight	1,369 kg
COE	\$84,000
OMV	\$22,380
ARF	\$23,332
Dereg Value	\$96,137 as of today
No. of Owners	1