

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 24.05.23

INSURANCE: ALLIANZ

MODEL: Hyundai i40

MVA: JUMANI

VEHICLE NO.: SHB4157A

D.O.A 14.05.23

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	REAR DOOR ASSY LH			\$2,201.10 <i>Rx</i>
	REAR FENDER LH			\$2,171.40 <i>Rx</i>
	ROCKER PANEL GARNISH RH			\$732.80 <i>Rx</i>
	REAR WHEEL RIM CAP			\$217.20 <i>our</i>
	REAR BUMPER ASSY			\$553.00 <i>Rx</i>
	SUB TOTAL			\$5,875.50
	LESS 25%			\$1,468.87
	DISCOUNTED TOTAL			\$4,406.63
	ADVERTISEMENT LOGO - 4 PCS			<i>ant</i> \$400.00 NET
	REAR DOOR APPS LOGO			<i>net</i> \$80.00 NET
	FRT DOOR COMFORT LOGO			<i>net</i> \$75.00 NET
				\$555.00
	Labour Charge			
	PANEL BEATING	1200		<i>560</i>
	SPRAYPAINT			<i>1100</i> \$1,200.00
	WIRING CHARGES			\$50.00 <i>X</i>
	TUFF KOTE			\$50.00 <i>X</i>
	REMOVE/REFIX DOOR PARTS			\$120.00 <i>X</i>
	TOTAL LABOUR			\$ 2,620.00
	ESTIMATE TOTAL			\$ 7,581.63

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin 97495949
25/5/23 2pm
4/5 Beating after repair
Tanjin c/khant.com
03 days

JK Auto Consultants hereby certify that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without-repair" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance company

Acknowledged by Repairer

Signature: _____

Date: _____

Date/Time: 24.05.2023 13:41

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5897892


JC NO305555721

OMER	REGN NO.: SHB4157A	MILEAGE
S COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
OMER NO. 7010045	MODEL I-40	E.....1/2.....F
ESS 383 SIN MING DRIVE	DATE/TIME IN	24.05.2023 10:45
Singapore SINGAPORE 575717	YR OF MANU. 29.10.2015	TARGET DATE
(R) 65508755 (O)	CHASSIS CODE KMHLB41UMGU080215	COMPLETION DATE/TIME:
(P)		
DUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 14.05.2023
NATURE: 3P.14.05.23

NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHB4157A

JU ALLIANZ

Vehicle No.:

SHB4157A

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard