SS2M233H0002 / SBS Transit Ltd [786010] ENTRY DATE & TIME: 17/03/2023 07:45 (SGT) SUBMITTED BY: Tham Meng Khuan VERSION: 1 (17/03/2023 07:45 (SGT))

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 17/03/2023 07:45 (SGT) Reported by **Actual Driver** Date of Accident 14/03/2023 06:50 (SGT) Exact Location of Accident Yishun Ave 2, Singapore Additional Location Information Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SMB3124S

#### INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner SBS TRANSIT LTD Company Reg No 199206653MPTE01 Email Address thammk@sbstransit.com.sg Mobile Phone No (Phone) +65-63754198 Alternative Phone No

#### VEHICLE PARTICULARS

Manufacturer Man Model MAN A22 EU5, SD, AC, 2 Axle Exact purpose for which vehicle was being used at time of accident Employment Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Bus Transmission Auto 10518

#### **INSURANCE COMPANY**

Name of Insurance Company MS First Capital Insurance Ltd Policy Number / Cover Note Number D-22099137MFBP

### DRIVER

Name of Driver Yeoh Jing Xian Passport No/FIN G2839920R Date Of Birth 08/08/1997 Occupation Outdoor



Date Of Driving Pass 23/12/2022 Driving experience 3 MONTHS Gender Male Mobile Number (Phone) +65-84059757 Alt. Phone Number Email Address thammk@sbstransit.com.sg Address No 340 Taman Tuan Sheikh Batu 1 Jalan Seremban Negeri Sembilan 71000 Address complement Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Side Swipe Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name **UNKNOWN** Gender Male PASSENGER 2 Name **UNKNOWN** Gender Female PASSENGER 3 Name **UNKNOWN** Male PASSENGER 4 Name **UNKNOWN** Gender Female PASSENGER 5 Name **UNKNOWN** Gender Male PASSENGER 6 Name **UNKNOWN** Gender Female

**DETAILS OF POLICE ACTION** 

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

I was travelling along Yishun Avenue 2 road that converged from 2 lane into 1 lane after bus stop 59069. On my right side, there was a TTS bus (SG6080S, svc 857) that horned my bus. I stopped my bus immediately. The left body of the latter side swipe the right mirror of my bus. We stopped to exchanged particulars and parted. No injury. That's all.

ATTACHMENT(S)

Are accident photos available for attachment? No Was there any video captured by Car Camera? No

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number       SG6080S         Vehicle Manufacturer       -         Vehicle Model       -         Vehicle Variant       -         Vehicle Colour       -         Vehicle Category       Bus
Vehicle Model - Vehicle Variant - Vehicle Colour - Vehicle Category Bus
Vehicle Variant - Vehicle Colour - Vehicle Category Bus
Vehicle Variant - Vehicle Colour - Vehicle Category Bus
Vehicle Colour - Vehicle Category Bus
Vehicle Category Bus
0 7
Name of Driver
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name
Nature Of Damage
Details of property damaged in accident NO DAMAGED, POI LEFT BODY
No. Of Passenger (Including Driver)