

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS3/SMO23005344/Knp3m4
	50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Date:	07/06/2023
	SINGAPORE LAND	J TOWERSINGAPORE 048023	Code:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SMM 4343L	Veh. Inspected	SFM 1881C
	Policy No.	D22MTPV01010519	Coverage (\$)	0.00
	Claim No.	CMTD2302101/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	25/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN ELGRAND (A)	c.c	2488
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JN1TBAE52Z0802476	Colour	METALLIC SILVER
	Odometer	94348 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	YOKOHAMA	8 mm
	L/H Front Tyre	225/55 R18	YOKOHAMA	8 mm
	R/H Rear Tyre	225/55 R18	YOKOHAMA	8 mm
	L/H Rear Tyre	225/55 R18	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.			
5. General Information				
	Accident Date	22/05/2023	Inspect Date / Time	25/05/2023 (01:30 PM)
	Survey held at	LIM MOTOR PTE LTD		
		160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722		
5a.	a. Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$10,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days			

Report Ref No. CS3/SMO23005344/Knp3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser