ASS. REC. BY: REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Veh No: SMF321M Yr Regn: 2020, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Freed c.c 1496

Colour Yellow A/C: Insured / Std / NI / NA

Sp.Reading 43636 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GB5109169 7

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R16

R: 205/50R16

	N/S	O/S
Remark: The veh had commenced its repair at the time of inspection.		

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Front		Rear	
R/Bal. 06	mm	R/Bal. 06	mm
L/Bal. 06	mm	L/Bal. 06	mm
D.O.A.		D.O.I. 23/05/23	

Survey held at JL Perfect.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front N/S, U/C.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Claim.
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during 1st Survey : Yes (✓) No ( )

764D

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

☐ : [illegible] ($

Survey Fee:

Transportation: S + RS. SI

Photos

Others

Report Format :

Main Form / LPR / [illegible]