



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC23005377/Kvp3e2

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 04-07-2023

Code: INC4

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | GBK 6645T      | Veh. Inspected | SHF 279L   |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1224669-002 | Excess (\$)    | 0.00       |
| Assign From  | ASHLENE LEE    | Assign Date    | 26/05/2023 |

#### 2. Vehicle Particulars & Condition

|              |                   |              |                    |
|--------------|-------------------|--------------|--------------------|
| Make & Model | TOYOTA PRIUS (A)  | c.c          | 1798               |
| Engine No.   | HIDDEN            | Year of Reg. | 2019               |
| Chassis No.  | JTDKB3FU003089467 | Colour       | METALLIC BROWN     |
| Odometer     | 203322            | Steering     | IN ORDER           |
| Brakes       | IN ORDER          | Modification | STANDARD ALLOY RIM |
| General      | GOOD              |              |                    |

#### 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 195/65 R15 | SAILUN | 9 mm    |
| L/H Front Tyre | 195/65 R15 | SAILUN | 9 mm    |
| R/H Rear Tyre  | 195/65 R15 | SAILUN | 9 mm    |
| L/H Rear Tyre  | 195/65 R15 | SAILUN | 9 mm    |

#### 4. Description of Damages

|                                                                                                   |
|---------------------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE.<br>DAMAGES SEE DETAILS. |
|---------------------------------------------------------------------------------------------------|

#### 5. General Information

|                |                                                     |                 |            |
|----------------|-----------------------------------------------------|-----------------|------------|
| Accident Date  | 24/05/2023                                          | Inspection Date | 26/05/2023 |
| Survey held at | STRIDES AUTOMOTIVE SERVICES PL.<br>ANG MO KIO DEPOT |                 |            |

#### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

#### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|