

Not Whatch
11 Ring &
Putty After Paint
5-7 days



ESTIMATE TO REPAIR

VEHICLE NO. : SLV 6509 C
MAKE : KIA
MODEL : CERATO K3 1.6A
YEAR : 2018
CHASSIS NO : KNAFZ411MJ5757654

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 25-May-23
DATE OF ACCIDENT : 22-May-23
THIRD PARTY REF : SLF 1803 U
THIRD PARTY REF : INDIA INTERNATIONAL INSURANCE

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear bumper				\$ 621.00
1 pc	Rear bumper reinforcement				\$ 287.00
2 pc	Rear bumper retainer				\$ 52.00
1 pc	Rear bumper reflector LH				\$ 90.00
1 pc	Rear bumper sensor				\$ 180.00
1 pc	Rear end panel				\$ 292.00
1 pc	Rear end panel garnish				\$ 52.00
1 pc	Tail lamp LH				\$ 789.00
1 pc	Rear boot lid				\$ 1,388.00
1 pc	Rear boot lamp LH				\$ 711.00
1 pc	Rear LH fender undershield				\$ 160.50
1 pc	Front bumper				\$ 634.00
1 pc	Front bumper reinforcement				\$ 448.00
2 pc	Front bumper retainer				\$ 40.00
1 pc	Front bumper sensor				\$ 180.00
1 pc	Front grille				\$ 296.00
1 pc	RH head lamp				\$ 2,369.00
					\$ 8,589.50
	Less 10%				\$ 858.95
					\$ 7,730.55
1 pc	Rear bumper lower spoiler	S/N			\$ 680.00
1 pc	Number plate	S/N			\$ 40.00
	To putty & spray paint				\$ 1,400.00
	To check front wiring & focus headlights				\$ 30.00
	To check rear wiring & water leakage				\$ 30.00
	To anti rust				\$ 80.00
	Labour charge				\$ 1,000.00
TG/ZX	TOTAL				\$ 10,990.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: