

ASS. REC. BY: Tauyph

REF:

CS/CT123005392/Tnp3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
☒	

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G1BF6183R Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV200 c.c.Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 128959 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYB4m 207 0120309

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim orTyre Size: F: 285 / R14R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Powador

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 1/6/23 05pmSurvey held at Rep by Mark

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B.L. (\$)