

02/1/23 Wof
ASS. REC. BY: [Signature]

REF: CS 3/HAB 23005433/Rvp3


4212

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBU 5198X
at Workshop m/s DYNASTY MOTOR
c. 50, BUKIT BATOK ST 23 #01-24
Insured: SHD 7097J HSH
Policy No. _____
Claims No. S3M04MRQ
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: FBU 5198X Yr Regn: 2022 / DKK
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda ADV 160 c.c. 157
Colour: RED A/C: Insured / Std / NI / NA
Sp. Reading: 9549 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MHIKEB213NK005712
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Mod: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 110/80-14
R: 130/70-13

(Policy Condition) H302ml pr
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: 19K
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FEDERAL

Front _____ Rear _____
R/Bal. 3 mm R/Bal. 4 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. 20/05/23 D.O.I. 30/05/23
Survey held at DYNASTY MOTOR
Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or _____

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
REPAIR LIMIT - 7K

5/6/23 ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 3 days

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 5/6/23-typist

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

) S + RS \$ _____

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	421Z
Vehicle Details	
Vehicle No.:	FBU5198X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jun 2023
Vehicle Make:	HONDA
Vehicle Model:	ADV 160
Primary Colour:	Red
Manufacturing Year:	2022
Engine No.:	KFB2E1005204
Chassis No.:	MH1KFB213NK005112
Maximum Power Output:	-
Open Market Value:	\$4,056.00
Original Registration Date:	20 Dec 2022
First Registration Date:	20 Dec 2022
Transfer Count:	1
Actual ARF Paid:	\$609.00
PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Rebate Details	
COE Expiry Date:	19 Dec 2032
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$12,589.00
COE Rebate Amount:	\$12,010.00
Total Rebate Amount:	\$12,010.00

The information contained herein is correct as at 04 Jun 2023

OK