

ASS. REC. BY: Taj

REF:

CS3/HSB 2300 S450/TVP3

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SHD 4692K

Policy No. _____

Claims No. S3M04MWP

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 4105K.

IDAC Accident Report _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24HRS

PMS - WP

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMJ 2990YYr Regn: 2019 / Feb.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Freed Hybrid

c.c

1496Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 319269

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 6571084064

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M/T / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 27/5/2023D.O.I. 30/5/23Survey held at Apex Auto fixing

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/6/23

Repair Range: 44000 - 45000, 6 days

Date/Time, File Pass to?

☐

: Prel. Report

i)

☐

: Final Report

Date/Time, File Return to?

2) 1/6/23-typist

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.R. /