

ASS. REC. BY: Marius

REF:

CC6/A1423005455/Upa3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBL 5675Hat Workshop m/s BHH

of _____

Insured: 50E 3633E

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 68k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUTDate: _____ Person Contacted: 21452177Veh No: FBL 5675HYr Regn: 27/12/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha MT-03AB c.c. 321Colour: silver/blue A/C: Insured / Std / NI / NASp. Reading: 38995 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3RH07K000005820Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 110-70ZR17R: 150-60ZR17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mm

L/Bal. mm

L/Bal. mm

D.O.A. 15/05/23D.O.I. 30/05/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & n/s B.L.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 2500ALPH 85823

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS SI

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	025G
Vehicle Details	
Vehicle No.:	FBL5675H
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2023
Vehicle Make:	YAMAHA
Vehicle Model:	MT-03 ABS (MTN320-A)
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	H402E0046326
Chassis No.:	MH3RH07K000005820
Maximum Power Output:	-
Open Market Value:	\$4,245.00
Original Registration Date:	27 Dec 2016
First Registration Date:	27 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$637.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,101.00
COE Rebate Amount:	\$2,177.00
Total Rebate Amount:	\$2,177.00

The information contained herein is correct as at 30 May 2023

OK


[Ad Choices](#)

Bike model	Type Of Vehicle	Price From	Price To	Class
YAMAHA MT-03	Any ☐	Any ☐	Any ☐	Any ☐

 Search

[More Search Options](#)

Sort By	Sort By
	Recommended ☐



Yamaha MT-03

Reg Date : 18/03/2016 Capacity : 321cc
 Vehicle Type : Street Bikes Mileage : 189191km

Posted on 22/03/2023

SGD \$7888

★ Paid Ad

★ Dealer Ad

[Details >](#)


Yamaha MT-03

Reg Date : 21/11/2018 Capacity : 321cc
 Vehicle Type : Street Bikes Mileage : 70000km

Posted on 28/04/2023

SGD \$11000

★ Direct Seller

[Details >](#)


Yamaha MT-03

Reg Date : 28/06/2019 Capacity : 321cc
 Vehicle Type : Street Bikes Mileage : 31500km

Posted on 24/04/2023

SGD \$12250

★ Direct Seller

[Details >](#)
[first](#)
[last](#)

Equipment

Wood Depot Sg

Bike Gadgets

[Number Plates for Sale](#)
[Installment Calculator](#)
[Instant Insurance Quote](#)

COE Results

Rd 2, 17 May 2023

COE Bidding of

Motorcycles

CAT D

\$10602

Wood Depot Sg

Consumables Available

OPEN

