Aspire 3 A314-32-C6Z5

ASS. REC. BY: Kenneth

REF: HSB/23005463/KP

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Thian HH

of 892N

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $300k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SNK1572K Yr Regn: 03, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A) Wagon

Make: Toy Alphard c.c 2493

Colour M Black A/C: Insured / Std / NI / NA

Sp.Reading 14445 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: AGH30 0434836

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	9 mm	R/Bal.	9 mm
L/Bal.	9 mm	L/Bal.	9 mm
D.O.A.	26/3/23	D.O.I.	30/5/2023

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or MS Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	GIA & EM not ready

Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Time, File Return to?

Survey Fee:

Transportation: $ + RS. $

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ Tech. Insp ($

t Format :