

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23005477/Uvy3m4	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Date	: 12/06/2023	
			Code	e: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJU 8016Z	Veh. Inspected	SNA 4849X	
	Policy No.	P10743229R00	Coverage (\$)	0.00	
	Claim No.	C10022572/SR	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	30/05/2023	
2. Vehicle Particulars & Condition					
	Make & Model	PEUGEOT 308 SW (A)	c.c	1199	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	VF3LRHNYWGS050552	Colour	WHITE	
	Odometer	128638 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55R16	YOKOHAMA	6 mm	
	L/H Front Tyre	205/55R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	205/55R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	205/55R16	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	29/05/2023	Inspection Date	30/05/2023	
	Survey held at	PROMPT AUTO SOLUTIONS P	TE LTD		
		8 KAKI BUKIT AVENUE 4 #02-37 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

**8 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: