

REPAIR ESTIMATE

Model : Prius (G4A)

MVA: MS. LOKE YY

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tough 97415749
 Wp 29/5/73 @ 430
 L/S Henry after report
 2 day
 Tough 01/11/2000.

Date:

Date/Time: 29.05.2023 10:07

Page : 1

nam: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5898358


JC NO305556032

CUSTOMER IS COMFORT TRANSPORTATION PTE LTD OWNER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) DUMENT CARD NO.	REGN NO. SHC2782C	MILEAGE
	MAKE TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4A29)	DATE/TIME IN 05.2023 09:15
	YR OF MANU. 28.11.2019	TARGET DATE
	CHASSIS CODE JTDKB3FU903089533	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 26.05.2023
NATURE: 3P 26.05.2023

/NO LABOR CODE DESCRIPTION



SIGNED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Edge of Slip

Exit Pass

No.: SHC2782C YY

Vehicle No.: SHC2782C

Service Advisor

Signature/Date

Name of Service Advisor

Date

Turned to Service Reception upon collection

To be kept by Security Guard