ASS. REC. BY: Tauffik | REF: CC4/AIS2300534/Jy93.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

WP

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Cm TS

Vehicle: IN / OUT

Veh No: SHA 6596H Yr Regn: 2021 / 1 Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover / Truck / Trailer or _____

Make: Hyundai Loniq c.c 1580

Colour: Blue. A/C: Insured / Std / NI / NA

Sp.Reading: 388823 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVL6419 2344

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or _____

Brake: (Inorder) / Jammed / Leaked / Burnt or _____

Modi: (NIL) / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/65R15

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	31/5/23

Survey held at Comfort Loyang

Des. of Damages : Frt / (Rear) / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) _____

Date/Time, File Return to? 2) _____

☐ : Prell. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Survey Fee:

Transportation: S + RS S

Photos

Others