

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23005553/Tqy3m4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	14-07-2023 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	XE 7668S	Veh. Ir	nspected	SG 5167H	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1226174-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	31/05/2023	
2. Vehicle Particulars & Condition						
	Make & Model	VOLVO B9TL	c.c		9364	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	YV3S4P922HA182110	Coloui	ſ	GREEN	
	Odometer	415728	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5	CONTI	NENTAL	8 mm	
	L/H Front Tyre	275/70 R22.5	CONTI	NENTAL	8 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	CONTI	NENTAL	8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	CONTI	NENTAL	8/8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S MIRROR.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	30/05/2023	Inspec	tion Date	31/05/2023	
	Survey held at	Survey held at STRIDES AUTOMOTIVE SERVICES PL.				
		60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a. Remarks						
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days					