

ASS. REC. BY:

REF:

1051

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

R Est Repairs:

days

Res.: Yes or No

Lum Sum:

1.3/20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Smk 528R

Yr Regn:

04, 19

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit

c.c

1317

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

81245

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

G1C3

1345943

Gen. Cnd: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

R: Falken

185/70R14

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/5/23

D.O.I.

1/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Work no 2nd part available.

Date/Time, File Pass to?



: Prell. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 29 May 2023)

Parts: 143

HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Alan's United Auto Pte Ltd/SMK5228R/29/05/2023 15:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*BONNET	Bu	0.00	0.00	*390.00 F	✓
2	1		*BONNET INSULATOR	CM	0.00	0.00	*95.00 F	✓
3	1		*BONNET INNER LOCK	R	0.00	0.00	*85.00 F	✓
4	2		*BONNET FRONT CENTRE RUBBER	W	0.00	0.00	*30.00 F	✓
5	2		*BONNET FRONT SIDE RUBBER	D/S	0.00	0.00	*26.00 F	✓
6	2		*BONNET HINGE	R	0.00	0.00	*104.00 F	✓
7	1		*FRONT BUMPER FASCIA	Bu	0.00	0.00	*570.00 F	✓
8	2		*FRONT BUMPER SIDE RETAINER	D/S	0.00	0.00	*32.00 F	✓
9	1		*FRONT BUMPER REINFORCEMENT		0.00	0.00	*195.00 F	?
10	1		*FRONT BUMPER LOWER GRILLE		0.00	0.00	*155.00 F	?
11	1		*FRONT BUMPER TOW COVER	R	0.00	0.00	*22.00 F	✓
12	2		*HEADLAMP	N/S CM	0.00	0.00	*960.00 F	✓
13	2		*HEADLAMP LOWER BRACKET		0.00	0.00	*84.00 F	?
14	1		*FRONT SUPPORT PANEL	R	0.00	0.00	*420.00 F	✓
15	1		*FRONT SUPPORT TOP COVER	D/S	0.00	0.00	*22.00 F	✓
16	2		*FRONT SUPPORT TOP COVER CLIP	M	0.00	0.00	*5.00 F	✓
17	1		*RADIATOR ASSY		0.00	0.00	*720.00 F	?
18	1		*RADIATOR FAN COWLING		0.00	0.00	*180.00 F	?
19	1		*RADIATOR SPARE TANK		0.00	0.00	*40.00 F	?
20	1		*AIR CON CONDENSER		0.00	0.00	*390.00 F	?
21	2		*AIR CON CONDENSER SIDE GUIDE		0.00	0.00	*64.00 F	?
22	1		*FRONT GRILLE BASE	CM	0.00	0.00	*240.00 F	✓
23	1		*FRONT GRILLE RH SIDE SCRENE	N	0.00	0.00	*25.00 F	✓
24	1		*FRONT GRILLE OUTER CHROME (TOP)	CM	0.00	0.00	*195.00 F	✓
25	1		*FRONT GRILLE LOGO	M	0.00	0.00	*26.00 F	✓
26	1		*FRONT GRILLE LOGO HOLDER		0.00	0.00	*28.00 F	?
27	1		*FRONT GRILLE LOWER CHROME	CM	0.00	0.00	*195.00 F	✓
28	1		*FRONT W/S GLASS WASHER TANK		0.00	0.00	*90.00 F	?
29	1		*AIR INTAKE HOSE		0.00	0.00	*55.00 F	?
30	1		*AIR DUCT	N	0.00	0.00	*35.00 F	✓
31	1		*TAIL GATE	R	0.00	0.00	*450.00 F	✓
32	1		*TAIL GATE FIT EMBLEM	M	0.00	0.00	*32.00 F	✓
33	1		*TAIL GATE GLASS MOULDING (SET)	M	0.00	0.00	*80.00 F	✓
34	1		*REAR BUMPER FASCIA	Bu/R	0.00	0.00	*280.00 F	✓
35	1		*REAR W/S GLASS SEALANT	M	0	0.00	40.00 *60.00 FS	✓
36	1		*FRONT NO.PLATE WITH BOX	R	0	0.00	45.00 *50.00 FS	✓
37	1		*RADIATOR COOLANT	M	0	0.00	*30.00 FS	✓
38	1		*FRONT BUMPER CLIP (SET)	M	0	0.00	*30.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	6,490.00
+ Margin on L,N Items 10.00% (\$\$)	632.00
Total Parts (\$\$)	7,122.00

Alan's United Auto Pte Ltd/SMK5228R/29/05/2023 15:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING FEE	New	60.00 ✓
2	TO REMOVE & REFIX REAR W/S GLASS AND CONDUCT WATER LEAK TEST	New	1200 150.00
3	TO REMOVE AIR CON CONDENSER, PIPES & DRIER, VACUUM AND TO RECHARGE GAS	New	100 120.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	950.00 ✓
5	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	New	800 900.00
Gross Labour Cost (\$)			2,180.00

Alan's United Auto Pte Ltd/SMK5228R/29/05/2023 15:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before filler spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party quotations on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	023118
Policy No:	MPC23P00077100	Date of Loss:	16/05/2023
Vehicle Reg. No.:	SMK5228R	Driveable?	
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	LAU NG KHIANG @ NG KHIANG ADRIAN	Contact No:	+6590705000
Driver:	LEE KIM YOONG		
Make/Model:	HONDA FIT, 1.3 GF CVT (A)	Vehicle Reg. Date:	12/04/2019
Vehicle Colour:	GREY	Chassis No:	GK31345943
Engine No:	L13B1454632		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8 ✓		
Present Location:	ALAN'S UNITED AUTO PTE LTD (HQ)		

*Not Withheld
Hlong & 1-B.1
Pehruy After Paint
B4*

COST OF CLAIMS

	Amount
Parts	7,122.00
Miscellaneous Items	0.00
Labour	2,180.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,302.00
+ GST 8.00% (S\$)	744.16
Nett Amount (S\$)	10,046.16

This claim is handled by: CHAN YEW SIAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 899G

Vehicle Details

Vehicle No.: SMK5228R
Vehicle to be Exported: Yes
Intended Deregistration Date: 18 May 2023
Vehicle Make: HONDA
Vehicle Model: FIT 1.3 GF CVT
Primary Colour: Grey
Manufacturing Year: 2018
Engine No.: L13B1454632
Chassis No.: GK31345943
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$15,094.00
Original Registration Date: 12 Apr 2019
First Registration Date: 12 Apr 2019
Transfer Count: 0
Actual ARF Paid: \$5,094.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 Apr 2029
PARF Rebate Amount: \$3,820.00

Intended COE Rebate Details

COE Expiry Date: 11 Apr 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$26,301.00
COE Rebate Amount: \$15,514.00
Total Rebate Amount: \$19,334.00

The information contained herein is correct as at 18 May 2023

OK

SA1E235G0001-01 / ALAN'S UNITED AUTO PTE LTD
ENTRY DATE & TIME: 16/05/2023 19:08 (SGT)
SUBMITTED BY: KHONG SHI JIE
VERSION: 2 (29/05/2023 13:54 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/05/2023 19:08 (SGT)
Reported by	Actual Driver
Date of Accident	16/05/2023 12:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	FILTER LANE FROM PIE EXIT TOWARDS TAMPINES AVE 5
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK5228R

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LAU NG KHIANG @ NG KHIANG ADRIAN
NRIC No	SXXXX899G
Email Address	MNBC2000@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-90705000
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Fit
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	0

INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Policy Number / Cover Note Number	MPC23P00077100

DRIVER

Name of Driver	LEE KIM YOONG
NRIC No	SXXXX596G
Date Of Birth	21/11/1977
Occupation	Indoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC card)

Sketch Plan

Diagram illustrating the accident location on a grid. The diagram shows a road layout with a filter lane from PIE (TOWARDS TAMPINES AVE 5). The locations are marked as follows:

- A = SMK 5228R
- B = SMP 1476R
- C = GBB 7116U

TAMPINES AVE 5