

(08/11/13) wef

ASS. REC. BY: Paul

REF:

CS/A91 23005590/Rvy3

5320

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 4185at Workshop m/s Ench Soonof 4, you tek IND EST 993-5Insured: A91

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 56k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 32KVeh No: SLR 4185 Yr Regn: 2017 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN PULSAR 1.2L D14-T c.c 1197Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 55020 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VS K02AC1340104156

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/50ZR17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 31/05/23D.O.I. 05/06/23

Survey held at

Ench Soon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT ML

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

) S + RS _____ \$

) Photos

) Others

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393-J
Woodlands Road
Singapore 677978
Tel: 67606271 Fax: 67646676

Date: 05/06/2023

Attn: Motor Claim Dept

Repair cost of Nissan Pulsar - SLR418S

SN	DESCRIPTION	AMOUNT
1	Front bumper <i>act</i>	\$ 1,614.70
2	Front bumper side bracket LH <i>act</i>	\$ 81.60
3	Front bumper fog lamp LH <i>sun</i>	\$ 322.60
4	Front bumper fog lamp garnish LH <i>sun</i>	\$ 304.70
5	Headlamp LH <i>sun</i>	\$ 1,511.90
	SUB TOTAL	\$ 3,835.50
	Less 10%	\$ 383.55
	SUB TOTAL	\$ 3,451.95
	SPECIAL NETT ITEM	
1	Front bumper clips <i>act</i>	\$ 30 60.00
2	Front parking sensor <i>act</i>	\$ 200 300.00
	SUB TOTAL	\$ 360.00
	LABOUR	
	Labour to remove & refit affected parts for front portion	\$ 200 500.00
	Spray paint on the affected parts for front portion	\$ 200 600.00
	To remove & refit parking sensor	\$ 40 80.00
	To conduct wiring check	\$ 30 50.00
	To apply anti rust coating	\$ X 60.00
	SUB TOTAL	\$ 1,290.00
	GRAND TOTAL	\$ 5,101.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Faru
Hp 90010068
3 days
4/5
05/06/23 @ 1620
Res after repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	532D
Vehicle No.:	SLR4185
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2023
Vehicle Make:	NISSAN
Vehicle Model:	PULSAR 1.2L DIG-T
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	HRA2428668A
Chassis No.:	VSKDDAC13U0104156
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$17,532.00
Original Registration Date:	28 Jul 2017
First Registration Date:	28 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$7,532.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2027
PARF Rebate Amount:	\$5,272.00
COE Expiry Date:	27 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$44,002.00
COE Rebate Amount:	\$18,121.00
Total Rebate Amount:	\$23,393.00

The information contained herein is correct as at 07 Jun 2023

OK

Nissan Pulsar 1.2A DIG-T

\$55,800 Instalment \$911/mth

 Shortlist  Get Warranty  Loan Calculator



Overview Financial Photo Research

Depreciation	 \$12,810 / year
Reg. Date	30-Jun-2017 (4yrs 22days COE left)
Manufactured	 2017
Mileage	-
Transmission	Auto
Engine Cap	1,197 cc
Road Tax	 \$508 / year
Power	85.0 kW (113 bhp) View specs of the Nissan Pulsar (2017-2017)
Curb Weight	 1,265 kg
COE	 \$42,801
OMV	 \$17,532
ARF	 \$7,532
Dereg Value	 \$22,663 as of today
No. of Owners	 1