

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12/14 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 93232546  
RISHIBARAJ MOHAN  
BLK 114 SIMEI STREET 1  
#07-624  
SINGAPORE 520114  
TEL : FAX :  
PH : 93232546  
ATTN :

## ESTIMATE BILL

Number : EB00006312  
Date : 31/05/2023  
Case No : AD00013919  
Vehicle No : SKH3563A  
Chassis: WBAWK52060PE13692  
Year of Mfr 2008  
Policy No 5129633526  
Model : BMW 320I AT 2.0L  
ABS D/AIRBAG 2WD

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	HEADLAMP RH	1.0	2,435.17	0	2,435.17
List Price - Parts Sub Total					2,435.17
2	FRONT BUMPER - REPAIR	1.0			
3	FRONT FENDER RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					2,435.17
4	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
5	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
6	WIRING	1.0	40.00	0	40.00
7	ANTI-RUST COATING	1.0	80.00	0	80.00
Labour 1 Sub Total					1,320.00
SINGAPORE DOLLARS : FOUR THOUSAND FIFTY-FIVE AND CENTS FIFTY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		3,755.17
			GST 8.00%		300.41
			TOTAL		4,055.58

Date of accident : 30/05/2023 09:50 PM. Place : CAUSEWAY

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	31/05/2023 11:27 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	30/05/2023 21:50 (SGT)
Exact Location of Accident	Near Woodlands Interchange, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH3563A
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	RISHIBARAJ MOHAN
NRIC No	SXXXX478B
Email Address	RISHIBARAJMOHAN@GMAIL.COM
Mobile Phone No	(Phone) +65-93232546
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	BMW
Model	320i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1995

#### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5129633526

#### DRIVER

Name of Driver	RISHIBARAJ MOHAN
NRIC No	SXXXX478B
Date Of Birth	30/03/1983
Occupation	Indoor

Date Of Driving Pass	17/11/2004
Driving experience	18 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93232546
Alt. Phone Number	-
Email Address	RISHIBARAJMOHAN@GMAIL.COM
Address	114 SIMEI STREET 1 #07-624
Address complement	-
Postcode	520114
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	S.AISHWARYA
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

I would like to report a hit and run at the Malaysian customs. I have dash cam footage of the incident. The vehicle SLW7054K driven by S0133841B side swiped my front right bumper. The driver did not exit his vehicle and continued driving even after I brought down my window to speak to him. As it was directly at the Woodlands entrance of the Malaysian CIQ, I did not want to block traffic as there were many vehicles entering the CIQ. After clearing Malaysian customs, I put on my hazard lights and waited for the vehicle at the side road to exchange particulars with the driver. The driver drove past me and sped off after noticing I was waiting for him. I then chased him down and caught up to him at the middle of the causeway. As I pulled along side him and signalled him to stop by the side of the road, he sped up and refused to stop.

His passenger in the front seat saw my gestures and refused to acknowledge me. As we pulled into Singapore Woodlands CIQ, I informed the ICA officers of the incident. They apprehended the driver but he still refused to get out of the car to exchange particulars for insurance claim purposes. The driver was then not allowed to exit the passport check area. The duty incident ICA officers were activated and both me and the driver were escorted to the ICA office. At the ICA office, the driver of SLW7054K was instructed to exchange particulars with me. The officer in charge was ASP Tan Yingguang. After exchanging particulars, the ICA officers cleared our passports and allowed us to leave.

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW7054K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
NRIC No	SXXXX841B
Contact Number	(Phone) +65-91784988
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

**Sketch Plan**

VECA: PKM 3563 A

VECB: CLW 7054 K

CAUSE WAY

Jun2022

1

REFER TO GIA REPORT

**Claim OD/TP at other workshop**

I/We declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)





**SINGAPORE  
POLICE FORCE**



T/20230531/7000

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 4

Report No. T/20230531/7000

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 31/05/2023 01:31	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

**Informant's Particulars**

Name of Informant: RISHIBARAJ MOHAN			Address:	
ID Type / ID No.: NRIC NO / S8308478B			Contact No.:	
			Home/Office:	Mobile: 93232546
Nationality: SINGAPORE CITIZEN			Email:	
			RISHIBARAJMOHAN@GMAIL.COM	
Sex: Male	Age: 40	Date of Birth: 30/03/1983	Type of Informant:	
			Driver	
Race: Indian			Language:	
			English	
Occupation: Management executive			Driving Licence Information:	
			Class:	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 30/05/2023 21:50	Type of Location: Straight Road
Location:  CAUSEWAY				
Weather: Clear	Road Surface: Dry			
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Heavy		
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction	Anyone conveyed by ambulance: No			

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SKH3563A	Car	BMW	320I A	Black		0
SLW7054K	Car			Grey	Slightly Damaged	2

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20230531/7000

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4

Report No. T/20230531/7000

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKH3563A	NTUC Income Insurance Co-Operative Limited	5129633526	26/08/2022	25/08/2023

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	RISHIBARAJ MOHAN	ID No.	S8308478B
Related Vehicle	SKH3563A (Car)	Contact No.	93232546
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Driver			
Name	Unknown Driver	ID No.	S0133841B
Related Vehicle	SLW7054K (Car)	Contact No.	91784988
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

## Brief Details.

I would like to report a hit and run at the Malaysian customs. I have dash cam footage of the incident. The vehicle SLW7054K driven by S0133841B side swiped my front right bumper. The driver did not exit his vehicle and continued driving even after I brought down my window to speak to him. As it was directly at the Woodlands entrance of the Malaysian CIQ, I did not want to block traffic as there were many vehicles entering the CIQ. After clearing Malaysian customs, I put on my hazard lights and waited for the vehicle at the side road to exchange particulars with the driver. The driver drove past me and sped off after noticing I was waiting for him. I then chased him down and caught up to him at the middle of the causeway. As I pulled along side him and signalled him to stop by the side of the road, he sped up and refused to stop. His passenger in the front seat saw my gestures and refused to acknowledge me. As we pulled into Singapore Woodlands CIQ, I informed the ICA officers of the incident. They apprehended the driver but he still refused to get out of the car to exchange particulars for insurance claim purposes. The driver was then not allowed to exit the passport check area. The duty incident ICA officers were activated and both me and the





**SINGAPORE  
POLICE FORCE**



T/20230531/7000

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 4

Report No. T/20230531/7000

**CONTINUATION OF REPORT**

driver were escorted to the ICA office. At the ICA office, the driver of SLW7054K was instructed to exchange particulars with me. The officer in charge was ASP Tan Yingguang. After exchanging particulars, the ICA officers cleared our passports and allowed us to leave.



**SINGAPORE  
POLICE FORCE**



T/20230531/7000

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

4 of 4

Report No. T/20230531/7000

**CONTINUATION OF REPORT**

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPB /  
IRMAN BIN MOHAMAD SAID  
Contact No.: 65476145

Signature Of Informant:

The identity of the person making this report has  
been authenticated by Singpass. No signature is  
required.

Date/Time:  
31/05/2023 01:31

Classification Of Case:

NP168