

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/1CS23005621/Uny3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F3C92347

at Workshop m/s B/H/H

of _____

Insured: SKW BMA

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: F3C92347 Yr Regn: 20/08/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha FZ150i c.c. 150

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 77849 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PMYK6025080002475

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or affected

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80-90-17 Maxxis

R: 110-80-17

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. mm

L/Bal. mm

D.O.A. 13/05/23

D.O.I. 5/6/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S, O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Body frame structure affected TOTAL LOSS
core used 30-11-2027

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	678F
Vehicle Details	
Vehicle No.:	FBC9234T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jun 2023
Vehicle Make:	YAMAHA
Vehicle Model:	FZ150I
Primary Colour:	Green
Manufacturing Year:	2008
Engine No.:	G372EE002475
Chassis No.:	PMYKG025080002475
Maximum Power Output:	-
Open Market Value:	\$2,390.00
Original Registration Date:	20 Aug 2008
First Registration Date:	20 Aug 2008
Transfer Count:	2
Actual ARF Paid:	\$359.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$5,005.00
COE Rebate Amount:	\$2,245.00
Total Rebate Amount:	\$2,245.00

The information contained herein is correct as at 05 Jun 2023

OK



toilet seat cover replacement

Open

Bike model

YAMAHA FZ 150

Type Of Vehicle

Any

Price From

Any

Price To

Any

Class

Any

Q Search

More Search Options

Sort By

Sort By

Recommended

No listings found.

first1last

Solutman trading

toilet seat cover replacement

OPEN

toilet seat cover replacement

Solutman trading

Bike Gadgets

- Number Plates for Sale
- Installment Calculator
- Instant Insurance Quote



carousell



Electronics Fashion Luxury Services Cars Property All Categories

Search for anything

All of Singapore

Advertisement

Motorcycles > Motorcycles for Sale > Class 2B



Yamaha fz150 2013 model

S\$2,500

 Dia
5.0

Used

Meetup

Premier@Kaki Bukit

Description

Bumped

1 week ago

Make

Yamaha

Type

Adventure

S\$ 2500

Pm for more information

Coe till 2023 December

Road tax just renewed 1 year

Engine Condition 9/10

Meet-up

Premier@Kaki Bukit