



Vehicle Information

CONDITION OF VEHICLE AT THE TIME OF SURVEY

CONDITION OF TYRES

Front Tyre Size	195/55 R15	Rear Tyre Size	195/55 R15
Front Left Side:(mm)	6	Rear Left Side:(mm)	6
Front Right Side:(mm)	6	Rear Right Side:(mm)	6

1. Surveyor name 2. Point of Impact /General Description of Damages 3. Vehicle Capacity 4. Mandate request amount

Repairer's Estimate(Gross)	:S\$	9554.50
Revised Amount	:S\$	4409.28
Check Items(Estimated)	:S\$	0.00
Total	:S\$	4409.28
Less	:S\$	
Total Loss Considetation		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE/PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	0.00

Remarks:

1/1