Ass. Ref. By: REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / MS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No:

at Workshop/s

of

Insured:

Policy No.

Claim No.

Insured: Excess:

Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBD9742M Yr Regn: 2015 / August.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 c.c 2488

Colour White. A/C: Insured / Std / NI / NA

Sp.Reading 28189 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1MC2E26Z0003174

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Windforce.

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	31/05/23.

Survey held at HD Perfect.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Chiner.
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during : Yes (✓)

1st Survey : No ( )

567D

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Inve ($)

Survey Fee:

Transportation: $ + RS. SI

Photos

Others