Our Job Ref		'No :	: 305556536 : 08/06/23			COMFORTDELGRO ENGINEERING ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156				
FINA	LIZATI	ON FO	RM				rai	C 6546 8156		
То	:LKI			LKK	K Fax			ı		
Attn	Attn : MrNaz_									
Vehic	de Reg	No.	; <u></u>	SHA4349T				04.06.2023		
The s	survey	and est	imates of	he repairs of the above	e-mentior	ed vehic	le are as folio	ws:-		
1.							SKK5861K			
2.	The f	inalized	amount s	hall be:			•			
	(a)	(a) Spare Parts after List discount								
	(b)	Labou	r Charges							
		Total	for Part-B	y-Part Repair Cost				\$0.00		
	(c.)	Total	for Lumps	ir (if applicable) um repair cost after Les n Repair cost	ss:	20%	-	\$1,250.00 \$1,250.00		
3.	Estimated normal period for repairs:				2	w	orking days.			
4.	We s	shall troorking o	eat the ab	ove amount as Correc	t and Co	nfirmed i	f there is no	reply from you within		
5.	Thai	nk you f	or your as	sistance.	We confirm the es					
	Sign	nature ;	Ms. Loke	<i>√</i> \	The second secon	SI	N:			
	Tel	ie .	6214835	**************************************			* ****	NAZ LKK		
	Fax	9.	6546815	consister and the second secon		De	ite 🖫	9/6/2023		
For	Officia									
101	Omon.	ar Ose (2111.7		In	cument				
		Item		Amount	A	cument ttached es or No	Confirm By (Signature)	Remarks		
1.	Rental	Rate P/	Day			YES				

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1. Rental Rate P/Day		YES			
2. Loss of Income Paid		NO		Support 184 Common Comm	
3. Survey Fees					
4. LTA Search Fee	\$26.75 / \$2.00				
5. Medical Fees (on behalf of driver, if applicable)					
6 Overrun					

Remarks	:			
				The state of the state of