

Our Job Ref No : 305556569  
Date : 08/06/23

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK  
Attn : Mr Naz  
Vehicle Reg No. : SHC8311P


Fax :


01.06.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME -- FBS2103A
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$746.12
  - (b) Labour Charges \$630.00
  - Total for Part-By-Part Repair Cost** \$1,376.12
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
Final Lumpsum Repair cost \$0.00
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature :   
Name : Ms. Loke YY  
Tel : 62148355  
Fax : 65468156

Signature :   
Name : NAZ LKK  
Date : 9/6/2023

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$26.75 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: