


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: SMU 79033
 at Workshop m/s VOLKSWAGEN
 of ALEXANDRA RD
 Insured: HLA
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection



Bal. or Market Value: 110k
 IDAC Accident Rpt: Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMU 79033 Yr Regn: 2020/ BWH
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: SKODA OCTAVIA 1.4 AMB c.c 1395
 Colour: BROWN A/C: Insured / Std / NI / NA
 Sp. Reading: 40634 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: TM BRC 7NE8 L0038/87
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SRM / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or NEXEN
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 20/05/23 D.O.I. 08/06/23
 Survey held at ALEXANDRA RD
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPORT LIMIT - 67K

We will be advising our principal a cost of repair P/P \$12,500.06 /- with 07 days
 of repair before GST, subject to their approval

(red, \$3685.35, 22%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) \$ + RS \$ _____

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Company
HL ASSURANCE PTE. LTD.
11 KEPPEL ROAD
#11-01 ABI PLAZA
Singapore 089057

Customer Details:
Mr
DOLLAH
AZMI BIN
BLK 12A MARSILING LANE
#16-57
SINGAPORE 731012

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
06-06-2023
5211032150
201229558W
30001
2023014854/ 1
01-06-2023
Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMU7903J	5E33MDA1	28-08-2020	TMBBC7NE8L0038187	OCTAVIA AMB TS110/1.4A7F	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#6	280.00 X	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00 ✓	518.40
5E0821105C	Fender	1	pcs.	845.49	#6	845.49	913.13
N 90959602	LHS FENDER 4?						
5E0821141A	Riveted Cap Nut	4	pcs.	2.64	#6	10.56	11.40
	Fender - B	1	pcs.	90.69	#6	90.69	97.95
	LHS FENDER BRACKET 3?						
5E2857507AC	Rear View	1	pcs.	1,351.30	#6	1,351.30	1,459.40
	LHS MIRROR HOUSING 3001						
5E0857537A GRU	Cap For Re	1	pcs.	119.67	#6	119.67	129.24
	LHS MIRROR COVER 3 repair						
5E0857521	Mirror Gla	1	pcs.	245.41	#6	245.41	265.04
	LHS MIRROR GLASS 3x						
5E0837477 5AP	Window Slo	1	pcs.	67.78	#6	67.78	73.20
	LHS FRT DOOR GLASS OUTER MLDG 3x						
5E5833055B	Unbekannt	1	pcs.	3,168.61	#6	3,168.61	3,422.10
	LHS REAR DOOR 3 repair						
5E5839697C	Door Seal,	1	pcs.	102.89	#6	102.89	111.12
D 378500A2	Alu-Lamin. Insulation 3x	1	pcs.	43.66	#6	43.66	47.15
	DOOR INSULATION 3x						
5J0867276	Clip	6	pcs.	2.05	#6	12.30	13.28
N 90263103	Unbekannt 3x	4	pcs.	0.53	#6	2.12	2.29
	RIVET NUT 3x						
5E0807905B	FOIL	1	pcs.	44.93	#6	44.93	48.52
	LHR FENDER FOIL 3x						
	LABOUR	5 ✓	pcs.	840.00	#6	4,200.00 4200	4,536.00
	SPRAY PAINT	5 ✓	pcs.	800.00	#6	4,000.00 ✓	4,320.00
	SPRAY MIRROR COVER	1	pcs.	280.00	#6	280.00 ✓	302.40
	TRANSFER DOOR MECHANISM	1	pcs.	840.00	#6	840.00 420	907.20
	HL DIRECT						
	DOA:20/5/2023						
	TP VEH NO: SNG110M						
	SURVEY BY:						

Quotation valid till 08-06-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	15,425.41	8%	1,294.83	16,185.41	17,480.24
Total	760.00	15,425.41		1,294.83	16,185.41	17,480.24

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company
HL ASSURANCE PTE. LTD.
11 KEPPEL ROAD
#11-01 ABI PLAZA
Singapore 089057

Customer Details:
Mr
DOLLAH
AZMI BIN
BLK 12A MARSILING LANE
#16-57
SINGAPORE 731012

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
06-06-2023
5211032150
201229558W
30001
2023014854/ 1
01-06-2023
Dass Anthonidas
Christopher

License plate
SMU7903J

Model code
5E33MDA1

First registration
28-08-2020

VIN
TMBBC7NE8L0038187

Model
OCTAVIA AMB TS110/1.4A7F

Mileage
20

Customer

Dass
Service Advisor

-----VISIT OUR WEBSITE aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram
Hp 90010068
7 days
08/06/23 @ 1015
Reg by paint

Supplementary or Omitted List



VEHICLE NUMBER: SMU7903J

MODEL: OCTAVIA

CLAIMS DETAILS

	LABOUR DESCRIPTION	Qty	Unit	Amount
1	SPRAY PAINTING <i>rw</i>	1	\$ 840.00	\$ 840.00
2				
3				
Total				\$840.00

No.	Item No.	Description	Qty	Unit Pricing	Discount	Amount
2						
11						
TOTAL:						\$0.00

Total Labour & Parts

\$840.00

Survey By

RASUL

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	147C
Vehicle No.:	SMU7903J
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jun 2023
Vehicle Make:	SKODA
Vehicle Model:	OCTAVIA 1.4 AMBITION TSI (A)
Primary Colour:	Brown
Manufacturing Year:	2019
Engine No.:	CZDA63202
Chassis No.:	TMBBC7NE8L0038187
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$18,870.00
Original Registration Date:	28 Aug 2020
First Registration Date:	28 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$18,870.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2030
PARF Rebate Amount:	\$14,152.00
COE Expiry Date:	27 Aug 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,802.00
COE Rebate Amount:	\$28,006.00
Total Rebate Amount:	\$42,158.00

The information contained herein is correct as at 08 Jun 2023

OK

Skoda Octavia 1.4A TSI Ambition

\$115,800 Instalment \$1,166/mth

PREMIUM AD

 BuySafe

 Shortlist

 Loan Calculator



Overview Financial Photo Research

Depreciation	 \$14,070 / year
Reg. Date	28-Dec-2020 (7yrs 6mths 18days COE left)
Manufactured	 2019
Mileage	58,800 km (24k / year)
Transmission	Auto
Engine Cap	1,395 cc
Road Tax	 \$624 / year
Power	110.0 kW (147 bhp) View specs of the SKODA Octavia (2018-2021)
Curb Weight	 1,289 kg
COE	 \$45,510
OMV	 \$18,870
ARF	 \$18,870
Dereg Value	 \$48,131 as of today

No. of Owners

 1