

ASS. REC. BY:

REF: MSG/230057101K943

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Autheave

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 810k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 09 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. 24 HRS

Date: 03/24 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJN 9374U Yr Regn: 03, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Traller or _____

Make: Hyundai Avante c.c. 1591

Colour: M. Silver A/C: Insured / Std / Nil / NA

Sp. Reading: 540082 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMH1DU 41BR94706002

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Mod: Nil / S/Rim / STD / R/Rim or _____

Tyre Size: F: _____ R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Giti

Front R/Bal. 7 mm Rear R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 3/6/23 D.O.I. 7/6/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Got B2</u>
<u>9/6/11 Pmp @ 2350h</u>	<u>Car used for 4113.29, 64%</u>

Date/Time, File Pass to? : Prell. Report : Final Report

1) Date/Time, File Return to? _____

2) _____

Days Of Repair: 4
Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
S - RS:	
Fees:	
Others:	
TOTAL:	

Report Format: MER-TP
Lump Sum / I.B.X. (\$) 2350

AUTHORIZE WORKSHOP PTE LTD

160, Sin Ming Drive, #03-19, Sin Ming Autocity, Singapore 575722

Tel: 64560226 Fax: 64584500

Registration No: 201603203R

<p>Mr Phang Siew Thong Blk 140 Bishan St 12, #08-490 Singapore 570140</p> <p>Attn:</p>	<p style="text-align: center;"><i>Not Authorised</i></p> <p style="text-align: center;"><i>11 Sep 8 23 50/2</i></p> <p style="text-align: center;"><i>Mercury After Paint</i></p> <p style="text-align: center;"><i>9 days</i></p> <p>Date : 7th June 2023</p> <p>Veh No : SJN 9374U</p> <p>Make/Model : Hyundai Avante</p> <p>Chassis No : KMHDU41BR9U706022</p> <p>Date of Acc : 03.06.23</p> <p>TP Veh No : SKM 8977E</p>
---	--

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Boot Lid <i>886</i>	\$ <i>By</i>	886.00 ✓
2	1 pc	Rear Boot Hyundai Logo	\$ <i>me</i>	32.90 ✓
3	1 pc	Rear Boot Lid Avante Emblem	\$ <i>me</i>	32.50 ✓
4	1 pc	Rear Boot Lid S Emblem	\$ <i>me</i>	25.60 ✓
5	1 pc	Rear Boot Lid Reflector Lamp RH	\$ <i>car</i>	126.20 ✓
6	1 pc	Rear Boot Mechanism Lock	\$ <i>R</i>	168.00 X
7	1 pc	Rear Boot Lid Inner Trim Board	\$ <i>in</i>	126.40 X
8	1 pc	Rear End Panel	\$ <i>R</i>	485.10 X
9	1 pc	Rear End Panel Top Garnish	\$ <i>in</i>	89.30 ✓
10	1 pc	Rear Boot Weatherstrip	\$ <i>in</i>	118.50 X
11	1 pc	Rear Spare Tire Panel	\$ <i>R</i>	825.40 X
12	1 pc	Rear Boot Lid Hinge Support Spring	\$ <i>in</i>	105.00 X
13	1 pc	Rear Lamp RH	\$ <i>me</i>	326.20 ✓
14	1 pc	Rear Bumper <i>582-20</i>	\$ <i>me</i>	582.20 ✓
15	2 pcs	Rear Bumper Side Retainer L/R	\$ 42.30	\$ <i>in</i> 84.60 X
16	2 pcs	Rear Bumper Bracket L/R	\$ 78.30	\$ <i>me</i> 156.60 X
16	1 pc	Rear Bumper Inner Sponge	\$ <i>cm</i>	\$ <i>opt</i> 141.40 ✓
17	1 pc	Rear Bumper Reinforcement	\$ <i>cm</i>	\$ 286.20 ✓
			\$	4,598.10
Less 10% :			\$	459.81
Parts Total :			\$	4,138.29
Special Nett				
1	1 set	Rear Bumper Clips	\$ <i>me</i>	45.00 ✓
2	1 set	End Panel Top Garnish Clips	\$ <i>me</i>	35.00 X
3	1 set	Trim Board Clips	\$ <i>me</i>	35.00 X
4	1 set	Reverse Sensor	\$ <i>short</i>	250.00 <i>300/-</i>
			\$	365.00
Labour				
1		To remove & rearrange electrical wirings, check lightings	\$	80.00 <i>200</i>
2		To remove, transfer boot lid components	\$	100.00 <i>500</i>
3		To remove, repair & replace damaged body parts, realign bodywork and where consistent to the accident.	\$	800.00 <i>4000</i>
4		Putty and respray painting on affected portions.	\$	800.00 <i>2000</i>
5		To remove & renew reverse sensor	\$	100.00 <i>500</i>
6		Rust proofing on affected portions.	\$	80.00 <i>300</i>
Labour :			\$	1,960.00
Total Parts & Labour :			\$	6,463.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

for Authorize Workshop Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	975A
Vehicle Details	
Vehicle No.:	SJN9374U
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U614272
Chassis No.:	KMHDU41BR9U706022
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,888.00
Original Registration Date:	05 Mar 2009
First Registration Date:	05 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$11,888.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Mar 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,763.00
COE Rebate Amount:	\$1,897.00
Total Rebate Amount:	\$1,897.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Jun 2023

OK

For Surveyor

SK0J23650005 / K. KIM HIN AUTO PTE LTD
ENTRY DATE & TIME: 05/06/2023 19:58 (SGT)
SUBMITTED BY: Sandra Khong
VERSION: 1 (05/06/2023 19:58 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/06/2023 19:58 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	03/06/2023 16:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE -EUNOS EXIT B4 EXIT 9
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN9374U
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	PHANG SIEW THONG
NRIC No	S1306975A
Email Address	DAVE.PHANG@GMAIL.COM
Mobile Phone No	(Phone) +65-94780327
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Avante
Variants	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5108352704-04

DRIVER

Name of Driver	PHANG SIEW THONG
NRIC No	S1306975A
Date Of Birth	19/02/1958
Occupation	Outdoor

Date Of Driving Pass	27/03/1981
Driving experience	42 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94780327
Alt. Phone Number	-
Email Address	DAVE.PHANG@GMAIL.COM
Address	BLK 140 BISHAN STREET 12 #08-490
Address complement	-
Postcode	570140
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	AFTER RAIN
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	GOJEK PASSENGER
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bishan Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005529999
Alt. Police Station Phone No	(Fax) +65-65561905
Police Station Address	20 Bishan Street 23 Singapore 579757
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	EMAIL INCOME

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM8977E
Vehicle Manufacturer	Toyota
Vehicle Model	Harrier
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	BENEDICT NG MIN ZHONG
NRIC No	S9022661D
Contact Number	(Phone) +65-96278518
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBE7577G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	WANG HUA WEI
NRIC No	S8757214E
Contact Number	(Phone) +65-90028977
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	PHANG SIEW THONG
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	NECK & LOWER BACK
Injured person in which vehicle?	SJN9374U
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GiA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



 5/6
 17
 Policyholder's Signature / Date & Time


 Actual Driver's Signature (if driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)



Sketch Plan



vJun2022




**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999



T/20230604/2054

1 of 4

Report No. T/20230604/2054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/06/2023 16:21	Vide Report No.:	Station Diary No.: 53
--	------------------	--------------------------

Informant's Particulars

Name of Informant: PHANG SIEW THONG		Address: APT BLK 140 BISHAN STREET 12 #08-490 SINGAPORE 570140	
ID Type / ID No.: NRIC NO / S1306975A		Contact No.:	Mobile: 94780327
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 65	Date of Birth: 19/02/1958	Type of Informant: Driver
Race: Chinese		Language: English	
Occupation: SOLE PROPRIETOR		Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 03/06/2023 16:30	Type of Location: Flyover
Location: PAN-ISLAND EXPRESSWAY				
Lamp Post Number: 460				
Weather: Others		Road Surface: Wet		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE7577G	Van	NISSAN	NV350 PANEL VAN 2.5 5AT 5DR EURO V	Silver		0
SJN9374U	Car	HYUNDAI	HD AVANTE 1.6 A	Silver		1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20230604/2054

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

2 of 4
Report No. T/20230604/2054

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKM8977E	Car	TOYOTA	HARRIER PREMIUM STYLE MAUVE 2.0 A	Purple		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJN9374U	NTUC Income Insurance Co-Operative Limited	5108352704-04	21/03/2023	20/03/2024

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	WANG HUAWEI	ID No.	S8757214E
Related Vehicle	GBE7577G (Van)	Contact No.	90028977
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	PHANG SIEW THONG	ID No.	S1306975A
Related Vehicle	SJN9374U (Car)	Contact No.	94780327
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	04/06/2023	Date Discharge	04/06/2023
No. of Days granted Medical Leave	07	Degree of Injury	NIL


**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999



T/20230604/2054

3 of 4

Report No. T/20230604/2054

CONTINUATION OF REPORT

Driver			
Name	BENEDICT NG MIN ZHONG	ID No.	S9022661D
Related Vehicle	SKM8977E (Car)	Contact No.	96278518
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 03rd June 2023 at about 4.30pm, I was driving my vehicle registration number: SJN9374U (V1) along PIE towards Eunos exit. I was driving at the extreme left lane with a female passenger (Gojek Booking ID: RB-148741-8596301). While I was driving, there was a vehicle that was in front of me stopped. I applied brake and stopped. V1 was in the stationary position.

Then, there was an impact came from the rear position. Due to the impact, my vehicle slightly moved forward. I was in pain due to THE impact. I alight slowly and realised another car: SKM8977E (V2) had collided to my rear portion. GBE7577G (V3) collided to V2's rear portion. I discovered that it was chain collision and total of 3 vehicles involved.

I took down all the particulars and send my passenger to her journey after that. Today, I was still in pain and went to seek medical attention. I was given 7 days MC and I'm lodging this report for Police to look into the matter.

Chain collision:

First car: SJN9374U (V1)
Second car: SKM8977E (V2)
Third car: GBE7577G (V3)



**SINGAPORE
POLICE FORCE**



T/20230604/2054

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

4 of 4
Report No. T/20230604/2054

CONTINUATION OF REPORT

Signature of Officer Recording The Report:
E /
SI MOHAMAD FARID BIN JAMAL

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SR STAFF SGT MUHAMMAD NOOR BIN
ABDUL RAHMAN
Contact No.: 65476219

Signature Of Informant:

Date/Time:
04/06/2023 16:21

Classification Of Case:

NP168