



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23005788/Unp3e2 Date: 06/07/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLL 1369A	Veh. Inspected	SFT 5377D
Policy No.		Coverage (\$)	0.00
Claim No.	C10022610/KY	Excess (\$)	0.00
Assign From	LEONG ENG MING	Assign Date	07/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	LEXUS RX450H (A)	c.c	3456
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTJBC11A902040933	Colour	BLACK
Odometer	171374 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/60 R18	PIRELLI	6 mm
L/H Front Tyre	235/60 R18	PIRELLI	6 mm
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	30/05/2023	Inspection Date	15/06/2023
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	