

COMFORTDELGRO ENGINEERING PTE LTD.

REPAIR ESTIMATE*

VEHICLE NO SHA8268S

DATE 05.06.2023

MAKE REG.31.05.2017

CHIANG/CHINA

MODEL TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			del \$503.04
1	REAR BUMPER SIDE RETAINER RH/ LH		\$112.70	? \$225.40
1	REAR BUMPER LOWER COVER			del \$654.96
1	REAR BUMPER TOWING COVER			? \$82.70
1	REAR REINFORCEMENT			? \$378.32
10	REAR BUMPER CLIPS		\$2.20	ney \$22.00
1	REAR TRUNK HYBRID EMBLEM			ney \$52.40
1	REAR TRUNK PRIUS EMBLEM			ney \$52.40
	SUB TOTAL			\$1,971.22
	25.00%			\$492.80
	DISCOUNTED TOTAL			\$1,478.41
1	BOOTLID COMFORT & TEL NO STICKER			ny \$60.00
1	BOOTLID COMFORT APP STICKER			ney \$40.00
1	REAR BUMPER ADVERTISEMENT			del \$50.00
2	REAR FENDER ADVERTISEMENT			ney \$200.00
1	REAR REVERSE SENSOR			ny \$135.70
				\$485.70
	Labour Charge			
	Panel Beating			525 \$875.00
	Spray Painting Charge			500 \$600.00
	Tuff Kote			X \$90.00
	Check Lighting			X \$60.00
	Remove/refix reverse sensor			30 \$90.00
	TOTAL LABOUR			\$1,715.00
	ESTIMATE TOTAL			\$3,679.11
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tauplin 97495749
 WP, 6/6/23 @ 315pm
 L/S Resurvey after repair
 Tauplin @ lkkauto.com
 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date/Time: 06.06.2023 09:56

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5899238

JC NO305556811

CUSTOMER

REGN NO.:

SHA8268S

MILEAGE

COMPANY CITYCAB PTE LTD

CUSTOMER NO. 7010070

ADDRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

TEL (R) 65551188

(O)

(P)

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)05.06.2023 16:45

DATE/TIME IN

YR OF MANU.

31.05.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU203557019

COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION


Accident Date: 05.06.2023

NATURE: 3P 05.06.2023

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Name:

No.:

Vehicle No.: SHA8268S

CHIANG

Exit Pass

Vehicle No.:

SHA8268S

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard