

INC

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

income (Lysam)

Date: 07.06.2023

Time: 12:24:24

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305556907
REGN NO : SH 6804R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 09.06.2016
DATE/TIME IN : 07.06.2023 10:25
ACCIDENT DATE : 06.06.2023

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER W LIP & FOG LAMP C	1	1,052.20	20.00	841.76	Rp
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	use
0003 04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	cut

SUB-TOTAL : 1,033.12

JOB NATURE

0000 L	PANEL BEAT	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	250

SUB-TOTAL : 600.00

TOTAL : 1,633.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE :

Tanfhi 97495749
up 7/6/23 @ 3:30pm
c/s Resurvey after repair
2 days
Tanfhi @ LK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: