

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD Ref: NS/INC23005806/Tnp3e2						
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	20-06-2023		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SDX 8562T	Veh. Ir	nspected	SHA 4226P	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1227676-001	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	07/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2022	
	Chassis No.	JTDKB3FU503096415	Coloui	r	BLUE	
	Odometer	220022	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST		6 mm	
	L/H Front Tyre	195/65 R15	WEST		6 mm	
	R/H Rear Tyre	195/65 R15	WEST		6 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	01/06/2023	Inspec	tion Date	07/06/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	. Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				