



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRES SINGAPORE
239924

Ref: CS/AGI23005813/Uvp3e2

Date: 03/07/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 2131U	Veh. Inspected	SJF 320B
Policy No.		Coverage (\$)	0.00
Claim No.	C10022713/JY	Excess (\$)	0.00
Assign From	LEONG ENG MING	Assign Date	08/06/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053ZEE106108691	Colour	BEIGE
Odometer	337198 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/06/2023	Inspection Date	08/06/2023
Survey held at	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------