

(08/11/13) wef

ASS. REC. BY: Marcus

REF:


CS/AG/23005813/4Vp3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJF 320B
at Workshop m/s Autikay
of SLT21314
Insured: _____
Policy No. _____
Claims No. C10022713/JY
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 848k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 10 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7156

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJF 320B Yr Regn: 15/105/08
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Toyota Corolla Altis 1598
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 337188 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MR0532EE-106128691
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: R5/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

| Front | Rear |
|------------------------|----------------------|
| R/Bal. <u>6</u> mm | R/Bal. <u>6</u> mm |
| L/Bal. <u>6</u> mm | L/Bal. <u>6</u> mm |
| D.O.A. <u>06/06/23</u> | D.O.I. <u>8/6/23</u> |

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|----------------|---|
| | <u>Rep 9K.</u> |
| | <u>Co insured 29-02-2028 LTA 19911</u> |
| | <u>3rd 54M.8m home towing 3.11 860</u> |
| | <u>After rep 16-06-23</u> |
| <u>27/6/23</u> | <u>4/5 @ 10,000 in hand vector (red 11,865.20, 54%)</u> |

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 10

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 28/6/23-typist

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

Report Format : TP

Lump Sum /+B+ (\$ 10,000)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| | |
|-------------------------------------|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 715B |
| Vehicle Details | |
| Vehicle No.: | SJF320B |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 08 Jun 2023 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | COROLLA ALTIS 1.6 AUTO |
| Primary Colour: | Silver |
| Manufacturing Year: | 2008 |
| Engine No.: | 3ZZ4766105 |
| Chassis No.: | MR053ZEE106108691 |
| Maximum Power Output: | 80.0 kW (107 bhp) |
| Open Market Value: | \$16,777.00 |
| Original Registration Date: | 15 May 2008 |
| First Registration Date: | 15 May 2008 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$16,777.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 29 Feb 2023 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| PQP Paid: | \$42,122.00 |
| COE Rebate Amount: | \$19,911.00 |
| Total Rebate Amount: | \$19,911.00 |

The information contained herein is correct as at 08 Jun 2023

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

Rare 2019 Honda Civic 1.0 Turbo.



Very Low Mileage, As Good As
New. UK Specs With Many
Features. Flexible Loan.
Car Lingual StarAd

Sort by [Date Posted](#) [20](#) results/page

12 vehicles



ALTIS 2028

Any Category

[Advanced Search](#)[Search](#)

| Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|------|-------|-------|--------------|----------|---------|---------|----------|--------|
|------|-------|-------|--------------|----------|---------|---------|----------|--------|

Search Selection

ALTIS 2028

Any

Any

> 10 year(s)
old

Any

Any

Any

Available



**Toyota Corolla Altis 1.6A (COE
till 04/2028)**

\$48,800

\$9,960 /yr

28-May-2008

1,598 cc

143,496 km

Sedan

Available

\$0 downpayment available. Flexible In-House Loan by GV Cars financing at 3.28% P.a. Approval within 24 hours. Add on 2 years warran...

GV Automobile Centre Pte Ltd

Posted: 07-Jun-2023

PREMIUM AD



**Toyota Corolla Altis 1.6A (COE
till 09/2028)**

\$63,800

\$12,130 /yr

10-Sep-2008

1,598 cc

138,299 km

Sedan

Available

\$0 downpayment available. 90% loan of the car price available by GV Cars financing at 3.28% in 24 hours. Add on 2 years warranty on...

GV Automobile Centre Pte Ltd

Posted: 07-Jun-2023

PREMIUM AD



**Toyota Corolla Altis 1.6A (COE
till 01/2028)**

\$45,800

\$9,850 /yr

26-Mar-2008

1,598 cc

143,299 km

Sedan

Available

\$0 downpayment available. Flexible In-House Loan by GV Cars financing at 3.28% P.a. Approval within 24 hours. Add on 2 years warran...

GV Automobile Centre Pte Ltd

Posted: 06-Jun-2023

PREMIUM AD



**Toyota Corolla Altis 1.6A (COE
till 12/2028)**

\$54,800

\$9,940 /yr

12-Dec-2008

1,598 cc

141,289 km

Sedan

Available

\$0 downpayment available. Flexible In-House Loan by GV Cars financing at 3.28% P.a. Approval within 24 hours. Add on 2 years warran...

GV Automobile Centre Pte Ltd

Posted: 06-Jun-2023

PREMIUM AD

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



**Toyota Corolla Altis 1.6A (COE
till 06/2028)**

\$50,800

\$10,030 /yr

15-Jul-2008

1,598 cc

155,484 km

Sedan

Available

\$0 downpayment available. 90% loan available by GV Cars financing at 3.28% in 24 hours. Add on 2 years warranty on engine and gear...

GV Automobile Centre Pte Ltd

Posted: 06-Jun-2023

PREMIUM AD

**Toyota Corolla Altis 1.6A (COE
till 09/2028)**

\$52,800

\$9,950 /yr

26-Sep-2008

1,598 cc

144,233 km

Sedan

Available

PREMIUM AD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|--|
| Date of Submission | 06/06/2023 17:01 (SGT) |
| Reported by | Actual Driver |
| Date of Accident | 06/06/2023 09:28 (SGT) |
| Exact Location of Accident | Near 59 Tampines Central 7, Singapore 528597 |
| Additional Location Information | TRAFFIC JUNCTION OF TAMPINES AVENUE 12 & TAMPINES AVENUE 9 |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJF320B |
| INSURED/POLICYHOLDER | |
| Is company? | No |
| Name Of Registered Owner | S ELANGO VAN |
| NRIC No | SXXXX715B |
| Email Address | elvgovan@hotmail.com |
| Mobile Phone No | (Phone) +65-81824574 |
| Alternative Phone No | - |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Toyota |
| Model | Corolla |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 1598 |

INSURANCE COMPANY

| | |
|-----------------------------------|----------------------|
| Name of Insurance Company | Lonpac Insurance Bhd |
| Policy Number / Cover Note Number | Z23VP05033110 |

DRIVER

| | |
|----------------|----------------------|
| Name of Driver | ELANGIREN ELANGO VAN |
| NRIC No | SXXXX012D |
| Date Of Birth | 21/03/1999 |

| | |
|--|----------------------|
| Occupation | Indoor |
| Date Of Driving Pass | 13/03/2018 |
| Driving experience | 5 YEARS AND 3 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-92712852 |
| Alt. Phone Number | - |
| Email Address | EE.KIREN11@GMAIL.COM |
| Address | 96 FLORA ROAD |
| Address complement | #08-53 |
| Postcode | 507007 |
| Is the driver the policyholder? | No |
| If No, Relationship of the Driver with the Insured | Child |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|-----------------|
| Type of Accident | Chain Collision |
| Weather Conditions | LIGHT DRIZZLE |
| Road Surface | Wet |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 3 |
| Was anybody injured in the Accident? | Yes |
| Was any injured conveyed to hospital by ambulance? | No |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 3 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |
| Translator's name | - |
| Translator's ID | - |
| Translator's phone number | - |
| Translator's email | - |
| Original language used in the statement | - |

PASSENGER 1

| | |
|--------|----------------|
| Name | MANOJ JEYAPALA |
| Gender | Male |

PASSENGER 2

| | |
|--------|-----------------|
| Name | LAM KE JYE LEON |
| Gender | Male |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

ON 06/06/2023 AT ABOUT 0928 HOURS, I WAS TRAVELLING ALONG TAMPINES AVENUE 12 TOWARDS TAMPINES AVENUE 9. AT THAT TIME, THE VEHICLE IN FRONT OF ME STOPPED AS THERE WAS ANOTHER VEHICLE MAKING A U-TURN IN FRONT. ON SEEING THAT I SLOWED DOWN MY VEHICLE (REGN NO: SJF320B) AND THEN CAME TO A STOP. MOMENTS LATER, I HEARD A VERY LOUD BANG AND FELT MY VEHICLE JOLTED FORWARD. I IMMEDIATELY REALISED THAT THE VEHICLE BEHIND ME (REGN NO: SLT2131U) HAD COLLIDED INTO THE REAR PORTION OF MY STATIONARY VEHICLE (SJF320B). THE IMPACT WAS SO GREAT THAT IT CAUSED MY VEHICLE TO MOVE FORWARD AND HIT THE REAR PORTION OF THE FRONT VEHICLE (REGN NO: SLE5351K). NEXT I ALIGHTED FROM MY VEHICLE TO CHECK ON THE DAMAGES, TOOK PHOTOS AND EXCHANGED PARTICULARS. LATER THE POLICE AND AMBULANCE CAME TO THE SCENE. AFTER ATTENDING TO THE REAR DRIVER AND ALL THE VERIFICATIONS, THEY LEFT THE SCENE.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLT2131U
 Vehicle Manufacturer Seat
 Vehicle Model Leon
 Vehicle Variant -
 Vehicle Colour Blue
 Vehicle Category Private car
 Name of Driver SIM BINGWEN DARIUS
 NRIC No SXXXX710G
 Contact Number (Phone) +65-87499467
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage FRONT PORTION DAMAGED
 Details of property damaged in accident FRONT PORTION DAMAGED
 No. Of Passenger (Including Driver) 3

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLE5351K
 Vehicle Manufacturer Honda
 Vehicle Model Odyssey
 Vehicle Variant -
 Vehicle Colour Black
 Vehicle Category Private car
 Name of Driver MAH GUAN HENG (MA YUANHENG)
 NRIC No SXXXX264Z
 Contact Number (Phone) +65-88099911
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage REAR PORTION DAMAGED
 Details of property damaged in accident REAR PORTION DAMAGED
 No. Of Passenger (Including Driver) 1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person SIM BINGWEN DARIUS
 Gender Male
 Phone No (Phone) +65-87499467
 Address -
 Address Complement -
 Post Code -
 Approximate Age Years Old -
 Injuries Sustained CUT ON THE FINGER
 Injured person in which vehicle? SLT2131U
 Were seat belts worn? Yes
 Was this injured conveyed to hospital by ambulance? No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time 06/06/23
1300HR's

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

REFER TO REPORT

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)
/ Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

[Signature]

06/06/23
1300 HRS

Lim Puay Hong Victor

Not Allowed
 8/6/23
 1/5 \$10,000/
 10 days

Regn No : SJF320B

Vehicle Make & Model : Toyota Corolla Altis

| ITEM NO | DESCRIPTION OF ITEMS | QUANTITY (Piece/Set) | UNIT PRICE (S\$) | AMOUNT (S\$) |
|--------------------|---|-------------------------|---------------------|-----------------|
| <u>List Items:</u> | | | | |
| 1 | Rear bootlid <i>Buc</i> | 1 | \$ 867.71 | \$ 867.71 |
| 2 | Rear boot rubber <i>twi</i> | 1 | \$ 97.75 | \$ 97.75 |
| 3 | Rear boot lock <i>Set</i> | 1 | \$ 454.75 | \$ 454.75 |
| 4 | Rear boot lock catch <i>11</i> | 1 | \$ 42.50 | \$ 42.50 |
| 5 | Rear bootlid reflectors <i>scr/cne</i> | 2 | \$ 76.50 | \$ 153.00 |
| 6 | Rear bootlid inner trim <i>Torn</i> | 1 | \$ 280.51 | \$ 280.51 |
| 7 | Rear boot centre garnish emblem <i>all</i> | 1 | \$ 63.76 | \$ 63.76 |
| 8 | Rear boot emblem (Corolla) <i>all</i> | 1 | \$ 51.30 | \$ 51.30 |
| 9 | Rear boot emblem (Altis) <i>all</i> | 1 | \$ 55.21 | \$ 55.21 |
| 10 | Rear taillamp <i>n/s cne</i> | 2 | \$ 323.70 | \$ 647.40 |
| 11 | Rear taillamp panel <i>Set o/s R</i> | 2 | \$ 385.00 | \$ 770.00 |
| 12 | Rear taillamp gasket <i>all/torn</i> | 2 | \$ 18.10 | \$ 36.20 |
| 13 | Rear end panel <i>body</i> | 1 | \$ 573.21 | \$ 573.21 |
| 14 | Rear end panel top garnish <i>twi</i> | 1 | \$ 225.38 | \$ 225.38 |
| 15 | Rear floor panel <i>R</i> | 1 | \$ 727.65 | \$ 727.65 |
| 16 | Rear floor panel top board <i>Torn</i> | 1 | \$ 288.75 | \$ 288.75 |
| 17 | Rear floor panel side sponge <i>11</i> | 2 | \$ 259.13 | \$ 518.26 |
| 18 | Rear bumper <i>Dis</i> | 1 | \$ 714.25 | \$ 714.25 |
| 19 | Rear bumper side retainer <i>Set</i> | 2 | \$ 123.13 | \$ 246.26 |
| 20 | Rear bumper inner bracket <i>Set</i> | 2 | \$ 51.34 | \$ 102.68 |
| 21 | Rear bumper reflector <i>n/s cne o/s 11</i> | 2 | \$ 73.25 | \$ 146.50 |
| 22 | Rear bumper reinforcement <i>sponge Torn</i> | 1 | \$ 278.21 | \$ 278.21 |
| 23 | Rear fender <i>R</i> | 2 | \$ 1,203.14 | \$ 2,406.28 |
| 24 | Rear fender shield <i>11</i> | 2 | \$ 210.39 | \$ 420.78 |
| 25 | Rear fender inner garnish <i>n/s Dis o/s 11</i> | 2 | \$ 323.55 | \$ 647.10 |
| 26 | Rear exhaust silencer <i>11</i> | 1 | \$ 851.30 | \$ 851.30 |
| 27 | Rear exhaust rubber <i>11</i> | 1 | \$ 33.50 | \$ 33.50 |
| 28 | Rear exhaust chrome pipe <i>11</i> | 1 | \$ 153.10 | \$ 153.10 |
| 29 | Rear exhaust heat shield <i>11</i> | 1 | \$ 121.30 | \$ 121.30 |
| 30 | Front bonnet <i>R</i> | 1 | \$ 894.20 | \$ 894.20 |
| 31 | Front bonnet insulator <i>11</i> | 1 | \$ 310.25 | \$ 310.25 |
| 32 | Front bonnet insulator clips <i>11</i> | 8 | \$ 5.00 | \$ 40.00 |
| 33 | Front bonnet rubbers <i>11</i> | 1 | \$ 40.95 | \$ 40.95 |
| 34 | Front bonnet hinges LH/RH <i>11</i> | 2 | \$ 72.75 | \$ 145.50 |
| 35 | Front bonnet lock <i>twi</i> | 1 | \$ 178.50 | \$ 178.50 |
| 36 | Front bonnet lock cable <i>11</i> | 1 | \$ 82.54 | \$ 82.54 |
| 37 | Front bonnet stand <i>11</i> | 1 | \$ 65.25 | \$ 65.25 |
| 38 | Front bumper <i>De</i> | 1 | \$ 695.64 | \$ 695.64 |
| 39 | Front bumper sponge <i>n/s</i> | 1 | \$ 120.75 | \$ 120.75 |
| 40 | Front bumper lower grille <i>Torn</i> | 1 | \$ 130.50 | \$ 130.50 |
| 41 | Front bumper fog lamps <i>covers twi</i> | 2 | \$ 130.32 | \$ 260.64 |
| 42 | Front bumper fog lamp & <i>cne</i> | 2 | \$ 366.00 | \$ 732.00 |
| 43 | Front bumper reinforcement <i>Set</i> | 1 | \$ 323.41 | \$ 323.41 |
| 44 | Front bumper side retainers LH/RH <i>Set</i> | 2 | \$ 61.10 | \$ 122.20 |
| 45 | Front fenders LH/RH <i>R</i> | 2 | \$ 517.45 | \$ 1,034.90 |

17,151.83

Regn No : SJF320B

Vehicle Make & Model : Toyota Corolla Altis

| ITEM NO | DESCRIPTION OF ITEMS | QUANTITY (Piece/Set) | UNIT PRICE (\$) | AMOUNT (\$) |
|----------------------------|--|-------------------------|--------------------|----------------------------|
| List Items: | | | | |
| 46 | Front fender innershields LH/RH <i>11</i> | 2 | \$ 90.40 | \$ 180.80 <i>X</i> |
| 47 | Front grille <i>one</i> | 1 | \$ 351.81 | \$ 351.81 <i>✓</i> |
| 48 | Front grille logo <i>one</i> | 1 | \$ 58.91 | \$ 58.91 <i>✓</i> |
| 49 | Front grille clips <i>11</i> | 5 | \$ 5.00 | \$ 25.00 <i>X</i> |
| 50 | Front grille top seal <i>one</i> | 1 | \$ 40.95 | \$ 40.95 <i>✓</i> |
| 51 | Front headlamp assembly LH/RH <i>one 845.10x2=</i> | 2 <i>1690.20</i> | \$ 924.79 | \$ 1,849.58 <i>✓</i> |
| 52 | Front headlamp lower brackets LH/RH <i>NS</i> | 2 | \$ 152.10 | \$ 304.20 <i>X</i> |
| 53 | Front headlamp chrome mountings LH/RH <i>NZ</i> | 2 | \$ 148.76 | \$ 297.52 <i>X</i> |
| 54 | Front support panel <i>3set</i> | 1 | \$ 467.10 | \$ 467.10 <i>✓</i> |
| 55 | Front support brace panel <i>1set</i> | 1 | \$ 52.50 | \$ 52.50 <i>✓</i> |
| 56 | Horns <i>11</i> | 2 | \$ 90.12 | \$ 180.24 <i>X</i> |
| 57 | Air con condenser <i>3set/2set</i> | 1 | \$ <i>1018.00</i> | \$ <i>1018.00</i> <i>✓</i> |
| 58 | Air con discharge pipe <i>11</i> | 1 | \$ 320.13 | \$ 320.13 <i>X</i> |
| 59 | Air con suction pipe <i>11</i> | 1 | \$ 280.51 | \$ 280.51 <i>X</i> |
| 60 | Air con liquid pipe <i>11</i> | 1 | \$ 315.19 | \$ 315.19 <i>X</i> |
| | | | Sub-total | \$ <i>22,894.27</i> |
| Less | | | 25% | \$ |
| List Items | | | Total | \$ <i>17,170.70</i> |
| Special Nett Items: | | | | |
| 1 | Rear bumper clips <i>all</i> | <i>42 1set</i> | \$ 5.50 | \$ 66.00 <i>30</i> |
| 2 | Rear boot inner trim board clips <i>all</i> | <i>8 1set</i> | \$ 5.50 | \$ 44.00 <i>30</i> |
| 3 <i>1set</i> | Reverse sensor <i>modification</i> | <i>1 set</i> | \$ 350.00 | \$ 350.00 <i>200</i> |
| 4 | Rear number plate with holder <i>3set</i> | <i>1</i> | \$ 55.00 | \$ 55.00 <i>40</i> |
| 5 | Front bumper clips <i>all</i> | <i>42 1set</i> | \$ 5.50 | \$ 66.00 <i>30</i> |
| 6 | Front fender innershield clips <i>11</i> | <i>15</i> | \$ 5.50 | \$ 82.50 <i>X</i> |
| 7 | Front bumper clips <i>repair</i> | <i>12 1set</i> | \$ 5.50 | \$ 66.00 <i>30</i> |
| 8 | Front number plate with holder <i>3set</i> | <i>1</i> | \$ 55.00 | \$ 55.00 <i>40</i> |
| S/Nett Items | | | Total | \$ 784.50 |

Labour Charge Items:

| | | |
|---------------|--|--------------------------|
| 1 | Towing charge | \$ 100.00 <i>60</i> |
| 2 | To check and rectify wirings | \$ 120.00 <i>30</i> |
| 3 | To replace reverse sensors and check. | \$ 120.00 <i>80</i> |
| 4 | To remove, refill aircon condenser and refill aircon gas | \$ 150.00 <i>100</i> |
| 5 | To rust proof affected areas | \$ 120.00 <i>90</i> |
| 6 | To renew damaged parts, replace and align all parts | \$ 1,600.00 <i>1500</i> |
| 7 | To putty, re-spray painting and polish rear affected areas | \$ 1,700.00 <i>1600</i> |
| Labour Charge | | Total \$ 3,910.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate Parts & Labour

Grand total \$ **21,865.20**

211651.48
282
2738.61