


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLE 8076K
 at Workshop m/s ETH02
 of BUKIT BARUK
 Insured: INDEPENDANT
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: S8K
 IDAC Accident Rpt: Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLE 8076K Yr Regn: 2016 / BUK
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: HYUNDAI LFSOMATA 2.0 GLS c.c 1999
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 52832 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KM HG 341 CMGA 262136
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / SRim / STD A/Rim or _____
 Tyre Size: F: 215/55R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 02/06/23 D.O.I. 08/06/23
 Survey held at ETH02
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 27K</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Report Format : _____
 Lump Sum / I.B.I.: (\$ _____)

Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))

Survey Fee: _____
 Transportation: _____
 S + RS. SI _____
 Photos _____
 Others _____
 TOTAL _____

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 08/06/2023

To :

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 02/06/2023

Vehicle No : SLE-8076-K Make & Model : HYUNDAI SONATA VIII 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BUMPER <i>form</i>	684.00	
1	REAR BUMPER LOWER GARNISH <i>CR</i>	288.00	
1	REAR BUMPER REFLECTOR <i>LH-X/RH-Ce</i>	144.00	
1	REAR BUMPER CENTRE REFLECTOR <i>scr</i>	504.00	
1	REAR BUMPER REINFORCEMENT <i>CR</i>	576.00	
2	REAR BUMPER RETAINER <i>new LH-X/RH-m</i>	57.60	
10	REAR BUMPER CLIPS <i>m</i>	50.00	
1	END PANEL <i>lt</i>	486.00	
1	END PANEL TOP GARNISH <i>de</i>	85.00	

Date : 08/06/2023

To :

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 02/06/2023

Vehicle No : SLE-8076-K

Make & Model : HYUNDAI SONATA VIII 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILLAMP RH <i>cm</i>	880.00	
1	REAR FENDER RH <i>repair</i>	1,350.00	
1	BOOT LID <i>sf</i>	1,230.00	
1	BOOT LID LOCK <i>bl</i>	171.00	
1	BOOT LID WEATHERSTRIP <i>m</i>	162.00	
1	BOOT LID LAMP RH <i>?</i>	670.00	
1	REAR LOGO <i>m</i>	65.00	
1	EMBLEM - SONATA <i>m</i>	72.00	
1	BOOT LID LOCK SWITCH <i>cm</i>	380.00	
2	BOOT LID NUMBER PLATE LAMP <i>X</i>	130.00	

Date : 08/06/2023

To :

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 02/06/2023

Vehicle No : SLE-8076-K

Make & Model : HYUNDAI SONATA VIII 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR EXHAUST SILENCER ?	1,400.00	
1	REAR BUMPER LOWER COVER GARNISH <i>cm</i>	76.00	
1	FRONT BUMPER <i>de</i>	690.00	
1	FRONT BUMPER LOWER GRILLE <i>de</i>	85.00	
2	FRONT BUMPER SIDE GARNISH RH/LH <i>LH-X/RH-?</i>	209.00	
2	DAYTIME RUN LAMP RH/LH ?	936.00	
1	FRONT BUMPER REINFORCEMENT ?	450.00	
1	FRONT BUMPER SPONGE ?	117.00	
2	FRONT BUMPER RETAINER <i>m</i>	68.00	
10	FRONT BUMPER CLIPS <i>m</i>	50.00	

Date : 08/06/2023

To :

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 02/06/2023

Vehicle No : SLE-8076-K

Make & Model : HYUNDAI SONATA VIII 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT GRILLE ASSY <i>ca</i>	530.00	
2	HEADLAMP RH/LH ?	5,120.00	
1	SUPPORT PANEL ASSY ?	820.00	
1	BONNET <i>BA</i>	1,620.00	
1	FRONT NUMBER BASE HOLDER <i>du</i>	50.00	
1	FRONT FENDER RH <i>repair</i>	685.00	
	Sub Total	20890.60	
	Discount 20% On Parts	(4178.12)	
	Special Nett Item		
1	REVERSE SENSOR <i>ca</i>	220.00	

Date : 08/06/2023

To :

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 02/06/2023

Vehicle No : SLE-8076-K

Make & Model : HYUNDAI SONATA VIII 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT NUMBER PLATE <i>51</i>	35.00	
1	REAR WINDSCREEN SEALANT <i>X</i>	50.00	
1	COOLANT <i>?</i>	50.00	
	Sub Total	355.00	
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	2,000.00	<i>1600</i>
	TO RESPRAY AFFECTED PORTION FRONT AND REAR	2,000.00	<i>1400</i>
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	150.00	<i>X</i>
	TO REMOVE AND TRASFER BOOT LID COMPONENTS	150.00	<i>60</i>

Date : 08/06/2023

To :

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 02/06/2023

Vehicle No : SLE-8076-K Make & Model : HYUNDAI SONATA VIII 2.0 GLS (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO TOP UP AIRCON GAS ?	150.00	100?
	RUST PROOFING	100.00	60
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30
	Sub Total	4600.00	
	<div style="border: 2px solid blue; padding: 5px; margin: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>	21,667.48	
	REMARKS:		
	<div style="border: 1px solid black; padding: 5px; margin: 5px;"> <p>12 days - p/p - Reg 50 paint</p> </div>		
	SUB TOTAL		
	GST 8.0 %	1,733.40	
	TOTAL	23,400.88	

Surveyor's name: Rasul - HP 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 08/06/23 @ 1510

Hyundai Sonata 2.0A GLS

\$62,000 Instalment \$1,166/mth

DIRECT OWNER

Apply for 2.28% loan

Shortlist

Get Warranty

Get a free personalised body assessment to see if you're the right fit.

Open

Overview Financial Photo Research

Depreciation	<i>i</i> \$15,130 / year
Reg. Date	21-Nov-2016 (3yrs 5mths 11days COE left)
Manufactured	<i>i</i> 2016
Mileage	56,000 km (8.5k / year)
Transmission	Auto
Engine Cap	1,999 cc
Road Tax	<i>i</i> \$1,212 / year
Power	113.0 kW (151 bhp) View specs of the Hyundai Sonata VIII (2014-2018)
Curb Weight	<i>i</i> 1,460 kg
COE	<i>i</i> \$56,500
OMV	<i>i</i> \$19,483
ARF	<i>i</i> \$19,483
Dereg Value	<i>i</i> \$32,168 as of today
No. of Owners	<i>i</i> 2

Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

943G

SLE8076K

No

08 Jun 2023

HYUNDAI

LF SONATA 2.0 GLS A/T

Grey

2016

G4NAGA526958

KMHE341CMGA262136

113.0 kW (151 bhp)

\$19,237.00

02 Aug 2016

02 Aug 2016

1

\$19,237.00

Yes

01 Aug 2026

\$12,504.00

01 Aug 2026

B - Car above 1600cc or 97kW (130bhp)

10

\$56,089.00

\$17,655.00

\$30,159.00

The information contained herein is correct as at 08 Jun 2023

OK