

ASS. REC. BY: Tauph

REF: CS3/INC23005832/Tay

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMM 6517 Yr Regn: 2019, June
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Renault Grand Scenic C.C. 1461
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 211652 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VF1RF400162894727
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/55 R20
 R: ~

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
	<input checked="" type="checkbox"/>

Bal. or Market Value: 492K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP' PMS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Touvalor
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 8/6/23 @ 1030
 Survey held at G13
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	09/06/23 submit prs

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Rep. Format: _____
 Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	