

(08/11/13) wef

ASS. REC. BY: Marcus

REF:


CS/1 NC23005834/UVY3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FBS 81507
 at Workshop m/s Ernst Lee
 of SKV2904M
 Insured: _____
 Policy No. _____
 Claims No. MT/1226023-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 4/2500
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 6526

Vehicle: IN / OUT

1A 7086

Veh No: FBS 81507 Yr Regn: 05/08/21
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha Aerox 155 c.c. 155
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 17307 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MH3SG 6420 MJ014506
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 110-80-14
 R: 140-70-14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or maxxis
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 03/06/23 D.O.I. 8/6/23
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
015 Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 1600not 8544check n/s body have damage?conf. and with repairing n/s no damage4/5 1800 informed AM Kien (red 2930, 61%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 4

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 13/6/23--typist

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / H.B.: (\$ 1800)


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	652B
Vehicle Details	
Vehicle No.:	FBS8150Z
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jun 2023
Vehicle Make:	YAMAHA
Vehicle Model:	AEROX155 ABS CVT
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	G3P4E0025947
Chassis No.:	MH35G6420MJ014506
Maximum Power Output:	-
Open Market Value:	\$2,442.00
Original Registration Date:	05 Aug 2021
First Registration Date:	05 Aug 2021
Transfer Count:	1
Actual ARF Paid:	\$367.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Aug 2031
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$8,689.00
COE Rebate Amount:	\$7,086.00
Total Rebate Amount:	\$7,086.00

The information contained herein is correct as at 08 Jun 2023

OK

**Yamaha Aerox 155**

Reg Date : 25/01/2022
Vehicle Type : Scooters


Capacity : 155cc
Mileage : -

SGD \$16800

Posted on : 19/05/2023

★ Paid Ad

★ Dealer Ad

[Details >](#)**Yamaha Aerox 155**

Reg Date : 27/02/2020
Vehicle Type : Scooters


Capacity : 155cc
Mileage : 128212km

SGD \$11588

Posted on : 20/05/2023

★ Paid Ad

★ Dealer Ad

[Details >](#)**Yamaha Aerox 155**

Reg Date : 11/10/2021
Vehicle Type : Scooters


Capacity : 155cc
Mileage : -

SGD \$12800

Posted on : 18/05/2023

★ Paid Ad

★ Dealer Ad

[Details >](#)**Yamaha Aerox 155**

Reg Date : 10/11/2020
Vehicle Type :

Capacity : 155cc

SGD \$10077

Posted on : 31/05/2023

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 7-Jun-23

Estimate no.

Plate No. FBS8150Z

Model. AEROX V2

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET <i>11</i>	\$ 450.00	X	
2	FORK T-UNDER BRACKET <i>11</i>	\$ 220.00	X	
3	STEERING CONE <i>11</i>	\$ 150.00	X	
4	HANDLE BAR <i>Set</i>	\$ 175 250.00	✓	
5	HANDLE COVER 1 <i>cut</i>	\$ 120.00	✓	
6	HANDLE COVER 2 <i>cut</i>	\$ 80 120.00	✓	
7	MIRROR SET <i>ols cut</i>	\$ 48 120.00	✓	
8	MIRROR BRACKET LEFT <i>11</i>	\$ 100.00	X	
9	BRAKE LEVER RIGHT <i>cut</i>	\$ 80.00	✓	
10	HANDLE BALANCER <i>cut</i>	\$ 35 50.00	✓	
11	FRONT DISC BRAKE <i>11</i>	\$ 150.00	X	
12	FRONT PANEL COVER <i>11</i>	\$ 115 150.00	✓	
13	FRONT PANEL INNER COVER <i>cut</i>	\$ 120.00	✓	
14	FRONT FAIRING COVER RIGHT <i>cut</i>	\$ 155 220.00	✓	
15	FRONT FAIRING INNER COVER RIGHT <i>cut</i>	\$ 80.00	✓	
16	FRONT FOOTREST BOARD RIGHT <i>cut</i>	\$ 120.00	✓	
17	REAR FOOTREST RIGHT <i>cut</i>	\$ 100.00	X	
18	RADIATOR COVER <i>cut</i>	\$ 120.00	✓	
19	EXHAUST PIPE <i>11</i>	\$ 500.00	X	
20	EXHAUST COVER <i>cut</i>	\$ 100.00	✓	
21	<i>slider</i> REAR BALANCER <i>cut</i>	\$ 280.00	✓	
22	REAR BOX <i>cut</i>	\$ 450.00	380 s/n	
23	REAR FAIRING COVER RIGHT <i>cut</i>	\$ 155 180.00	✓	
24	LABOUR	\$ 500.00	300	

102

Sub Total : \$ 4,730.00
 GST 8% \$ 340.56
 Total: \$ 4,597.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.

not Authorized
 her
 mercus
 90096608
 8/6/23
 2/5 1800/
 Take 2nd. Atk. man
 4 days

P-1783
 102
 1604.70
 380
 300