

(DA/11/13) wsf
ASS. REC. BY: pm

REF: CC4/MS23005879/Rgas

9639

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 1714 L

at Workshop m/s GOLD BEL

of 8, TWA ME 18

insured: AIS

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 41K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBF 1714 L

Yr Regn: 2016 / July

Type: M.Car / M.Cycle / Bus / Van / Corp / Taxi / Prime Mover /

Truck / Trailer or

Make: MIDWAY FURNITURE c.c. 2498

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 128455 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PEAD1BA20283

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 7 -

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7/7 mm

L/Bal. 7 mm

L/Bal. 7/7 mm

D.O.A. 07/06/23

D.O.I. 12/06/23

Survey held at

GOLD BEL

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REMOVE LINK - 33K

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

) \$ + RS \$

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	963G
Vehicle No.:	GBF1714L
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2023
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEA01BR1SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C26231
Chassis No.:	FEA01BA20283
Maximum Power Output:	-
Open Market Value:	\$29,378.00
Original Registration Date:	20 Jul 2016
First Registration Date:	20 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$1,469.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	19 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,239.00
COE Rebate Amount:	\$7,519.00
Total Rebate Amount:	\$7,519.00

The information contained herein is correct as at 12 Jun 2023

OK

Mitsubishi Fuso Canter FEA01

\$40,800 Instalment \$1,124/mth

 Shortlist

 Loan Calculator



Overview Financial Photo Research

Depreciation	 \$13,420 / year
Reg. Date	27-Jun-2016 (3yrs 14days COE left)
Lifespan	 26-Jun-2036
Manufactured	 2016
Mileage	-
Transmission	Manual
Engine Cap	2,998 cc
Curb Weight	 2,100 kg
Fuel Type	Diesel
COE	 \$48,002
OMV	 \$31,488
ARF	 \$1,575
Dereg Value	 \$14,598 as of today
No. of Owners	 4
Type of Veh	Truck