

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road  
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email:

tanpw@cdge.com.sg;kelvinsukwen@cdge.com.sg;oisunpin@cdge.com.sg;joharibh@sparkcarcare.com;kristytay@sparkcarcare.com

INSURER: **India International Insurance Pte Ltd (HQ)**

## PARTICULARS OF CLAIM

|                     |                                  |                       |            |
|---------------------|----------------------------------|-----------------------|------------|
| Claim Type:         | OD (OWN DAMAGE)                  | Ref. No:              |            |
| Policy No:          | D20MFL0000326_02                 | Date of Loss:         | 30/05/2023 |
| Vehicle Reg. No.:   | SLZ2271S                         | Driveable?            |            |
| Driver Age/Info:    |                                  | Party At Fault:       | UNKNOWN    |
| TP Injury Involved? | NO                               | Third Party Involved? | YES        |
| Insured/Claimant:   | COMFORTDELGRO RENT-A-CAR PTE LTD |                       |            |

|                 |                  |                    |                   |
|-----------------|------------------|--------------------|-------------------|
| Make/Model:     | MAZDA 3, 1.5 (A) | Vehicle Reg. Date: | 26/04/2018        |
| Vehicle Colour: | SILVER           | Chassis No:        | JM6BN22A8J0194335 |
| Engine No:      | P520486479       |                    |                   |
| Odometer:       | 0 KM             |                    |                   |

|                               |          |
|-------------------------------|----------|
| Paint Type:                   |          |
| List Item Discount:           | 20.00 %  |
| Total Loss?                   | NO       |
| Est. Duration of Repair (day) | 8 3 days |

*NOT Authorised  
Repair Body  
Ex TRA*

Present Location: **COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)**

## COST OF CLAIMS

|                          | Amount          |
|--------------------------|-----------------|
| Parts                    | 6,770.40        |
| Miscellaneous Items      | 41.00           |
| Labour                   | 850.00          |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>7,661.40</b> |
| <b>+ GST 8.00% (S\$)</b> | <b>612.91</b>   |
| <b>Nett Amount (S\$)</b> | <b>8,274.31</b> |

This claim is handled by: **OI SUN PIN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# REPAIR DETAILS

## Reference

|                                                                                               |                                                                                                                                                                              |
|-----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                                                    | Version: 1.0 (Last Synchronised: 08 Jun 2023)                                                                                                                                |
| <b>Parts:</b> 144                                                                             | MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)                                                                                                                            |
| <b>Labour:</b> Repairer's                                                                     | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> ComfortDelGro Engineering Pte Ltd/SLZ2271S/08/06/2023 16:09                |                                                                                                                                                                              |
| <b>Validity:</b>                                                                              | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *. |                                                                                                                                                                              |

## Estimates on Parts

| No. | Qty | Part No. | Particulars                      | %Disc | %Depr | Amount        |   |
|-----|-----|----------|----------------------------------|-------|-------|---------------|---|
| 1   | 1   |          | *FRONT BUMPER                    | 20.00 | 0.00  | CM *995.00 FL | ✓ |
| 2   | 1   |          | *FRONT BUMPER TOP PANEL          | 20.00 | 0.00  | R *378.00 FL  | ? |
| 3   | 1   |          | *FRONT RADIATOR GRILLE           | 20.00 | 0.00  | CM *164.00 FL | ✓ |
| 4   | 1   |          | *FRONT LH CHROME GARNISH         | 20.00 | 0.00  | CM *232.00 FL | ✓ |
| 5   | 1   |          | *FRONT RH CHROME GARNISH         | 20.00 | 0.00  | R *232.00 FL  | X |
| 6   | 1   |          | *FRONT LH CHROME GARNISH BRACKET | 20.00 | 0.00  | *180.00 FL    | ? |
| 7   | 1   |          | *FRONT RH CHROME BRACKET         | 20.00 | 0.00  | R *180.00 FL  | X |
| 8   | 1   |          | *FRONT BUMPER LOWER GRILLE       | 20.00 | 0.00  | R *165.00 FL  | X |
| 9   | 1   |          | *FRONT NUMBER PLATE BRACKET      | 20.00 | 0.00  | CM *75.00 FL  | ✓ |
| 10  | 1   |          | *FRONT GRILLE EMBLEM             | 20.00 | 0.00  | R *75.00 FL   | ✓ |
| 11  | 1   |          | *FRONT BUMPER LH FOGLAMP         | 20.00 | 0.00  | *761.00 FL    | ? |
| 12  | 1   |          | *FRONT BUMPER LH FOGLAMP COVER   | 20.00 | 0.00  | R *28.00 FL   | X |
| 13  | 1   |          | *FRONT REINFORCEMENT BAR         | 20.00 | 0.00  | *577.00 FL    | ? |
| 14  | 1   |          | *FRONT REINFORCEMENT BAR COVER   | 20.00 | 0.00  | *85.00 FL     | ? |
| 15  | 1   |          | *LH LED HEADLAMP                 | 20.00 | 0.00  | *4,336.00 FL  | ? |

F=Franchise part. L=ListItemDisc.

|                                       |                 |
|---------------------------------------|-----------------|
| Sub Total (S\$)                       | 8,463.00        |
| - List Item Discount on L Items (S\$) | 1,692.60        |
| <b>Total Parts (S\$)</b>              | <b>6,770.40</b> |

ComfortDelGro Engineering Pte Ltd/SLZ2271S/08/06/2023 16:09. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

No Qty Particulars

Amount

## Miscellaneous Items

|   |   |                      |
|---|---|----------------------|
| 1 | 1 | FRONT BUMPER CLIPS   |
| 2 | 1 | OD/TP Case (Insurer) |

30.00  
11.00

Sub Total (\$\$) 41.00

# Estimates on Labour

No Particulars

Lab.Type

Amount

## Labour Items

|   |                                                                               |
|---|-------------------------------------------------------------------------------|
| 1 | To knock & straighten on accident area, to remove & refit Front damage parts. |
| 2 | To putty & respray on Front damage area.                                      |
| 3 | To check wiring, focus headlamp.                                              |

New

400.00

New

400.00

New

50.00

Gross Labour Cost (\$\$) 850.00

ComfortDelGro Engineering Pte Ltd/SLZ2271S/08/06/2023 16:09. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: