

ASS. REC. BY:

REF:

TMI / 2300 5893 / Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

837,845/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 599IR

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

269401

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J7OK B3FU 403 077 290

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

Wanli 195/65R15

R:

Pavlon

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

8

mm

L/Bal.

6

mm

L/Bal.

8

mm

D.O.A.

7/6/23

D.O.I.

8/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S / R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/6 21h @ 8700h Cebu (Red, \$ 7460.74, 46%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fuel

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

878K

Vehicle Details

Vehicle No.:

SHD5991R

Vehicle to be Exported:

Yes

Intended Deregistration Date:

07 Jun 2023

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)

Primary Colour:

Red

Manufacturing Year:

2018

Engine No.:

2ZR2B79786

Chassis No.:

JTDKB3FU403077290

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,605.00

Original Registration Date:

12 Dec 2018

First Registration Date:

12 Dec 2018

Transfer Count:

0

Actual ARF Paid:

\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Dec 2026

PARF Rebate Amount:

\$10,685.00

Intended COE Rebate Details

COE Expiry Date:

11 Dec 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$22,057.00

COE Rebate Amount:

\$9,679.00

Total Rebate Amount:

\$20,364.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Jun 2023

OK

Not Withheld
 11 Rmp @ 8700/h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5991R

AAD2306-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

08 JUN 2023

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 EXTENSION, FRONT BUMPER, LH
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 LOUVER SUB-ASSY, COWL TOP VENTILATOR
- 1 PROTECTOR, COWL TOP VENTILATOR LOUVER
- 1 PANEL, INSTRUMENT PANEL FINISH, END RH
- 1 GLASS, WINDSHIELD
- 1 MOULDING, WINDSHIELD, OUTSIDE RH
- 1 HOOD SUB-ASSY
- 1 LOCK ASSY, HOOD
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH
- 1 LAMP ASSY, FOG, LH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 COVER SUB-ASSY, FRONT PILLAR, UPR RH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 BRACE SUB-ASSY, FENDER APRON, RH
- 1 APRON ASSY, FRONT FENDER, RH

Aditya

SHD5991R

JTDKB3FU403077290

200303878K

TOYOTA

PRIUS

7/6/2023

YN1576D/ Tokio.

12/12/2018

LIST

\$	Tu	653.31	✓
\$	CM	100.17	✓
\$	B	902.16	✓
\$	R	151.41	X
\$	Re	114.98	✓
\$	Pr	436.38	X
\$	Pl	214.41	X
\$	Pr	37.07	X
\$	R	59.85	✓
\$	Di	74.97	✓
\$	Aditya	865.83	✓
\$	mi	20.58	✓
\$	Pr	146.37	X
\$	CM	1,993.53	✓
\$	Re	107.73	✓
\$	R	1,243.20	✓
\$	R	170.31	X
\$	R	74.34	✓
\$	R	74.34	✓
\$	mgm	1,200.78	✓
\$	Br	3,325.56	✓
\$	Di	126.74	✓
\$	R	1,236.69	✓
\$	R	368.24	X
\$	R	222.71	X

Trans-cab Auto Services Pte Ltd

AAD2306-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5991R

- 1 EMBLEM, SIDE PANEL LH
- 1 LINER, FRONT FENDER, LH
- 1 RIM

\$	<i>me</i>	68.88	✓
\$	<i>Tn</i>	255.36	✓
\$	<i>in</i>	1,995.11	X
TOTAL	\$	16,240.99	
25%	\$	4,060.25	
	\$	12,180.74	

Special Nett

- 1 FRT BUMPER CLIP
- 1 FENDER CLIP
- 1 FENDER LINER CLIP
- 1 FRT LH BUMPER RETAINER CLIP

TOTAL

\$	<i>me</i>	65.00	<i>65.00</i>
\$	<i>nn me</i>	130.00	X
\$	<i>me</i>	130.00	<i>65.00</i>
\$	<i>nn</i>	65.00	X
\$		390.00	

TOTAL PARTS \$ 12,570.74**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *500*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *800*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *60*

To Check Electrical Lighting Concerned.

\$ 170.00 *20***TOTAL \$ 3,590.00****Over All Total \$ 16,160.74**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting (PART-BY-PART) Repair Days
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

08 days
4 days