

-  Service Requests
-  Messages
-  Claims

 Service Request Details

Claim	S3M04N20
Reference	CS3/HSB23005899/Kqp3m4 
Loss Date	5 June 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	7 Jun 2023 8:34:13 AM
Request Date	9 June 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information

Incident	SKD367R
Vehicle	
Registration #	
Make	TPVD Mercedes
Model	C180

Service Address

'''

Primary Contact/Insured

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME	DATE UPLOADED			
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 HSB-LKKInvoice-AC2303829.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	16 June 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	16 June 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	16 June 2023
 SKD367R IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 June 2023
 REPLY FORM SOLICITOR.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	9 June 2023
 SDH1681M GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	7 June 2023
 SDM9060B GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	7 June 2023
 SNE2970U GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	7 June 2023
 SMX123Z GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	7 June 2023
 SMF4945L GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	7 June 2023

