

ASS. REC. BY:

REF:

T4 / 23005923/ky

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/6

11pm @ 9000 Colm

Veh No:

SHD9460E Yr Regn: 08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

309215

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU60 308 2748

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

Gravelander 195/65R15

R:

Pailua

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

6

mm

L/Bal.

P

mm

L/Bal.

6

mm

D.O.A.

10/5/23

D.O.I.

12/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Warranted
L1Pp \$900k

Trans-cab Auto Services Pte Ltd

AAD2305-053

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9460E

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

12 JUN 2023

SHD9460E

JTDKB3FU603082748

200303878K

TOYOTA

PRIUS

10/5/2023

CB7134E/III

16/8/2019

PART

- 1 COVER, FRONT BUMPER
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 UNIT ASSY, HEADLAMP, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 FRONT FENDER EMBLEM RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 HOOD SUB-ASSY
- 1 HINGE ASSY, HOOD, LH
- 1 HINGE ASSY, HOOD, RH

LIST

\$	BU/W	516.00	✓
\$	in	80.10	X
\$	in	219.10	X
\$	in	2,637.60	X
\$	n	977.80	X
\$	in	206.70	X
\$	in	54.60	✓
\$	in	219.10	X
\$	n	983.10	X
\$	n	58.90	X
\$	n	58.90	X

TOTAL \$ 4,691.90
25% \$ 1,172.98
\$ 3,518.93

Special Nett

- 1 FRT BUMPER CLIP
- 1 FRT BUMPER SIDE RETAINER CLIP
- 1 FENDER LINER CLIP

\$	na	65.00	60sa
\$	na	65.00	X
\$	na	75.00	X

TOTAL \$ 205.00

TOTAL PARTS \$ 3,723.93

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *na* 250.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,800.00 *4401*

Trans-cab Auto Services Pte Ltd**AAD2305-053**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9460E

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *101*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,000.00 *2001*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To transfer of rear fender panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL \$ 4,990.00****Over All Total \$ 8,713.93****(PART-BY-PART) Repair Days****03 Days***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

878K

Vehicle Details

Vehicle No.:

SHD9460E

Vehicle to be Exported:

Yes

Intended Deregistration Date:

10 May 2023

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)

Primary Colour:

Red

Manufacturing Year:

2018

Engine No.:

2ZR2C43475

Chassis No.:

JTDKB3FU603082748

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,605.00

Original Registration Date:

16 Aug 2019

First Registration Date:

16 Aug 2019

Transfer Count:

0

Actual ARF Paid:

\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

15 Aug 2027

PARF Rebate Amount:

\$10,685.00

Intended COE Rebate Details

COE Expiry Date:

15 Aug 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$23,463.00

COE Rebate Amount:

\$12,504.00

Total Rebate Amount:

\$23,189.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 May 2023

OK