

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23005938/Rqy3e2	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	04/08/2023	
	ATTN: CYNTHIA A	NG		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLZ 2190S	Veh. Inspected	t	SLP 954X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1226804-002	Excess (\$)		0.00	
	Assign From	HAZALYSA	Assign Date		12/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3 SEDAN 1.5 AT S/R	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6BN22A8H0154361	Colour		BLACK	
	Odometer	384614 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE		6 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE		6 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE		6 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
					1.	
5.	5. General Information					
	Accident Date	09/06/2023	Inspect Date /	Time	12/06/2023 (11:45 AM)	
	Survey held at	PEGASUS ENGINEERING & TR	ADING PTE LTD			
		74 KIAN TECK ROAD SINGAPORE 628800				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		8 Worki	ing Days	