

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Terry Tan Soon Lee @huiri Amita
27 Olive Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 06/06/2023

WIP No. . : 22671

Veh.In/Out: 05/06/2023

*Tel.No. . : Mobile: 98421589

Reg.No. . : SMN2639S

Reg.date . : 30/07/2019

Mileage .. : 0

Chassis No: YV1ZW10ACL1347073

Singapore 298264

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Terry Tan Soon Le

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER,FRT LH FENDER, FRT LH DOOR,REAR LH DOOR,REAR LH FENDER,REAR BUMPER,ETC	0	8500.00	0		8,500.00	S
800	TO PUTTY SPRAY PAINT ON FRT BONNET,FRT BUMPER,FRT LH FENDER,FRT LH PILLAR,FRT LH DOOR,REAR LH DOOR,REAR LH FENDER,REAR BUMPER,ETC	0	7500.00	0		7,500.00	S
802	TO TRANSFER FRONT LH & REAR LH DOOR PARTS	0	500.00	0		500.00	S
802	TO REMOVE & INSTALL INTERIOR P	0	1700.00	0		1,700.00	S
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	850.00	0		850.00	S
89994	TO INSTALL REAR LH QUARTER GLASS FILM	0	280.00	0		280.00	S
031	TO REPLACE FRONT LH RIM	0	50.00	0		50.00	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Terry Tan Soon Lee @huiri Amita
27 Olive Road

GST Reg.No:M28920628X

Inv.No. . . : B&P 0 Page 2

Inv.date. . : 06/06/2023

WIP No. . . : 22671

Veh.In/Out: 05/06/2023

*Tel.No. . . : Mobile: 98421589

Reg.No. . . : SMN2639S

Reg.date . : 30/07/2019

Mileage . . : 0

Chassis No: YV1ZW10ACL1347073

Singapore 298264

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Terry Tan Soon Le

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
10	COMPUTERISED WHEEL ALIGMENT	0	280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE	0	570.00	0		570.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
R16	TOWING CHARGES	0	250.00	0		250.00	S
	BUMPER COVER FRT RD	1.0 EA	2487.40			2,487.40	S
	V032132220/RADIATOR	1.0 EA	991.20			991.20	S
	BUMPER BRACKET FRT L	1.0 EA	95.50			95.50	S
	BUMPER BRACKET FRT R	1.0 EA	95.50			95.50	S
	BUMPER CLIP GREEN S6	10.0 EA	6.00			60.00	S
	BUMPER BRACKET FRT L	1.0 EA	95.50			95.50	S
	BUMPER BRACKET FRT R	1.0 EA	95.50			95.50	S
	BUMPER FOAM ALL SV60	1.0 EA	143.20			143.20	S
	BUMPER BRACKET FRT A	3.0 EA	71.10			213.30	S
	BUMPER UNDER TRAY S6	1.0 EA	215.70			215.70	S
	BUMPER GUIDE SV60 2	2.0 EA	45.70			91.40	S
	BUMPER CLIP S80 07-	10.0 EA	6.00			60.00	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Terry Tan Soon Lee @huiiri Amita
27 Olive Road

GST Reg.No:M28920628X

Inv.No. . . : B&P 0 Page 3

Inv.date. . : 06/06/2023

WIP No. . . : 22671

Veh.In/Out: 05/06/2023

*Tel.No. . . : Mobile: 98421589

Reg.No. . . : SMN2639S

Reg.date . : 30/07/2019

Mileage .. : 0

Chassis No: YV1ZW10ACL1347073

Singapore 298264

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Terry Tan Soon Le

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	MESH GRILLE LH RD SV	1.0 EA	269.60			269.60	S
	MESH GRILLE RH RD SV	1.0 EA	269.60			269.60	S
	MESH BRACKET LH RD S	1.0 EA	66.40			66.40	S
	MESH BRACKET RH RD S	1.0 EA	66.40			66.40	S
	BUMPER GRILLE LOWER	1.0 EA	377.40			377.40	S
	BUMPER GRILLE SEAL A	1.0 EA	88.90			88.90	S
	TOW COVER FRT RD B4	1.0 EA	89.80			89.80	S
	NUMBER PLATE RETAINE	1.0 EA	78.00			78.00	S
	V032277114/CROSS MEM	1.0 EA	226.70			226.70	S
	STAY	1.0 EA	84.70			84.70	S
	STAY	1.0 EA	84.70			84.70	S
	BRACKET LH TOP PANEL	1.0 EA	75.80			75.80	S
	FENDER PANEL FRT LH	1.0 EA	1433.00			1,433.00	S
	V031468231/FENDER CA	1.0 EA	253.30			253.30	S
	FENDER BRACKET FRT L	1.0 EA	72.60			72.60	S
	SPACER FENDER LH S60	1.0 EA	26.80			26.80	S
	INSULATING MAT FENDE	1.0 EA	367.50			367.50	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Mr Terry Tan Soon Lee @huiri Amita
 27 Olive Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 4

Inv.date. : 06/06/2023

WIP No. . : 22671

Veh.In/Out: 05/06/2023

*Tel.No. . : Mobile: 98421589

Reg.No. . : SMN2639S

Reg.date . : 30/07/2019

Mileage .. : 0

Chassis No: YV1ZW10ACL1347073

Singapore 298264

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Terry Tan Soon Le

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FOAMBLOCK LH	1.0 EA	78.00			78.00	S
	WHEEL ARCH LINER LH	1.0 EA	280.70			280.70	S
	MUDFLAP LH	1.0 EA	62.30			62.30	S
	BUMPER CLIP 8x8,5	10.0 EA	9.00			90.00	S
	COVER AIR GUIDE	1.0 EA	1099.10			1,099.10	S
	AIR GUIDE OUTER S60	1.0 EA	367.50			367.50	S
	AIR GUIDE RADIATOR S	1.0 EA	142.60			142.60	S
	HEADLAMP LED LH S60	1.0 EA	3456.50			3,456.50	S
	FOG LAMP LH SV60 20-	1.0 EA	254.60			254.60	S
	MIRROR PANEL LH T5RD	1.0 EA	213.90			213.90	S
	DOOR MIRROR LH T5RD	1.0 EA	1132.20			1,132.20	S
	MIRROR GLASS LH S90	1.0 EA	493.60			493.60	S
	MIRROR BACK COVER LH	1.0 EA	530.90			530.90	S
	FRONT DOOR PANEL LH	1.0 EA	2553.70			2,553.70	S
	TRIM PANEL BLACK FRT	1.0 EA	245.50			245.50	S
	A TRIM MOULDING LH S	1.0 EA	213.90			213.90	S
	SEAL STRIP DOOR FRT	1.0 EA	285.10			285.10	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Terry Tan Soon Lee @huiri Amita
27 Olive Road

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 5

Inv.date. : 06/06/2023

WIP No. . : 22671

Veh.In/Out: 05/06/2023

*Tel.No. . : Mobile: 98421589

Reg.No. . : SMN2639S

Reg.date .: 30/07/2019

Mileage .. : 0

Chassis No: YV1ZW10ACL1347073

Singapore 298264

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Terry Tan Soon Le

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	S60 20- RD GUIDE MOU	1.0 EA	285.10			285.10	S
	S60 20- RD TRIM MOUL	1.0 EA	316.30			316.30	S
	HANDLE OUTER LH XC40	1.0 EA	267.30			267.30	S
	ZV0890100070/NOISE D	1.0 EA	625.10			625.10	S
	REAR DOOR PANEL RH V	1.0 EA	2580.60			2,580.60	S
	TRIM PANEL BLACK REA	1.0 EA	281.70			281.70	S
	TRIM PANEL REAR LH	1.0 EA	153.70			153.70	S
	TRIM PANEL REAR LH	1.0 EA	245.00			245.00	S
	V60 20- SEAL STRIP D	1.0 EA	285.10			285.10	S
	GUIDE MOULDING REAR	1.0 EA	285.10			285.10	S
	TRIM MOULDING REAR L	1.0 EA	316.30			316.30	S
	NOISE DEADENING PAD	1.0 EA	625.10			625.10	S
	HINGE REAR LH UPPER	1.0 EA	227.20			227.20	S
	HINGE REAR LH LOWER	1.0 EA	227.20			227.20	S
	DOOR STOP REAR	1.0 EA	169.30			169.30	S
	ROCKER MOULDIND LH S	1.0 EA	730.60			730.60	S
	D PAINT PRIMER 30m	1.0 EA	102.70			102.70	S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Terry Tan Soon Lee @huiiri Amita
27 Olive Road

GST Reg.No:M28920628X

Inv.No. . . : B&P 0 Page 6

Inv.date. . : 06/06/2023

WIP No. . . : 22671

Veh.In/Out: 05/06/2023

*Tel.No. . . : Mobile: 98421589

Reg.No. . . : SMN2639S

Reg.date . . : 30/07/2019

Mileage . . : 0

Chassis No: YV1ZW10ACL1347073

Singapore 298264

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Terry Tan Soon Le

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	ADHESIVE SEALANT	1.0 EA	204.40			204.40	S
	RUST OFF SPECIAL NSF	1.0 EA	63.40			63.40	S
	ALLOY RIM 18 XC60 19	1.0 EA	1363.80			1,363.80	S
	FENDER PANEL REAR LH	1.0 EA	2571.30			2,571.30	S
	BODY PANEL SEALANT	1.0 EA	825.10			825.10	S
	QTR GLASS LH V60 20-	1.0 EA	1013.00			1,013.00	S
	D WINDSCREEN SEALA	1.0 EA	177.90			177.90	S

Gross Total. 54,497.80

Labour Total 20,480.00
Parts Total 34,017.80
Package Total 0.00

Net..... 54,497.80
 GST @ 8.0% 4,359.82
 Total..... 58,857.60
 Paid..... 0.00
 Please Pay.. 58,857.60

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate

2871

SJ0G235U000J-01 / JP Knights Pte Ltd
ENTRY DATE & TIME: 30/05/2023 11:31 (SGT)
SUBMITTED BY: Weine Chieng
VERSION: 2 (03/06/2023 15:36 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/05/2023 11:31 (SGT)
Reported by	Actual Driver
Date of Accident	29/05/2023 10:30 (SGT)
Exact Location of Accident	Andrew Rd, Singapore
Additional Location Information	TOWARDS CALDECOTT ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN2639S

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TERRY TAN SOON LEE @ HUIRI AMITA
NRIC No	SXXXX157G
Email Address	TERRY.TAN@BESTFORDGROUP.COM
Mobile Phone No	(Phone) +65-98421589
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Volvo
Model	V60
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1969

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMPG22010158

DRIVER

Name of Driver	HARRISFAZILA BIN ZAIDI @KHALEL YOGANANDA @ANANDA MAITREYA
NRIC No	SXXXX714Z
Date Of Birth	01/07/1972

Occupation	Indoor
Date Of Driving Pass	19/05/2016
Driving experience	7 YEARS
Gender	Male
Mobile Number	(Phone) +65-83884999
Alt. Phone Number	-
Email Address	TERRY.TAN@BESTFORDGROUP.COM
Address	27 OLIVE ROAD
Address complement	-
Postcode	298264
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Friend
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 29/05/2023 AROUND 1030HRS I WAS DRIVING VEHICLE A (SMN2639S) ALONG OLIVE ROAD JUNCTION TURNING RIGHT TO ANDREW ROAD , AS I REACHING ANDREW ROAD THERE WAS THIS ROAD WORK/PLUMBING WORK WAS GOING ON WITH ONE ROAD WAS BLOCKED , AS I COULDN'T SEE THAT THERE WAS A TRAFFIC CONTROLLER WAS A THE SIDE BECAUSE OF VEHICLE B (XD6509E) WAS BLOCKING IT I USE THE ALTERNATIVE WAY FOR ME TO PASS TRU , AT THE TIME I WAS HALF WAY DRIVING TRU VEHICLE B DRIVE OUT AND CHANGE LANE WITHOUT CHECKING THE BLINDSPOT AND COLLIDED ON TO MY LEFT SIDE PORTION AND GRAZED IT TILL THE BACK . NONE OF US WERE INJURED DURING THE ACCIDENT.

- 1) There was road works. And heavy vehicles at the side.
- 2) One road was blocked. So I used the alternative way for me to pass.
- 3) Just as I was halfway thru, Vehicle B drove out and change lane without checking blind spot. I did not see any indicator lights coming on on Vehicle B.
- 4) Only after the accident happened, and I got off the car, then the traffic light was visible. It was completely covered by Vehicle B.
- 5) We do have video captured by car camera.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD6509E
Vehicle Manufacturer	Mitsubishi
Vehicle Model	Fuso
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	TANSY
Contact Number	(Phone) +65-96741989
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) Investigating the accident and/or my claims.
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(Collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan




Driver's Signature (if driver is not the policyholder) / Date & Time

FLASH ACCIDENT REPORTING OFFICER
FRO VICKY



Witnessed by Reporting Centre Personnel

29/05/2023--1845HRS




Describe Circumstances of the Accident

ON 29/05/2023 AROUND 1030HRS I WAS DRIVING VEHICLE A (SMN2639S) ALONG OLIVE ROAD JUNCTION TURNING RIGHT TO ANDREW ROAD , AS I REACHING ANDREW ROAD THERE WAS THIS ROAD WORK/PLUMBING WORK WAS GOING ON WITH ONE ROAD WAS BLOCKED , AS I COULDN'T SEE THAT THERE WAS A TRAFFIC CONTROLLER WAS A THE SIDE BECAUSE OF VEHICLE B (XD6509E) WAS BLOCKING IT I USE THE ALTERNATIVE WAY FOR ME TO PASS TRU , AT THE TIME I WAS HALF WAY DRIVING TRU VEHICLE B DRIVE OUT AND CHANGE LANE WITHOUT CHECKING THE BLINDSPOT AND COLLIDED ON TO MY LEFT SIDE PORTION AND GRAZED IT TILL THE BACK . NONE OF US WERE INJURED DURING THE ACCIDENT.

Declaration

We declare the foregoing particulars are true in every respect.




Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time
29/05/2023 - 1845HRS

FLASH ACCIDENT
REPORTING OFFICER
FRO VICKY



Witnessed by Reporting Centre Personnel