

(08/11/13) wef

ASS. REC. BY: MARCUS

REF:

CS / CT / 23005948 / U923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F3T92867

at Workshop m/s BMH

of _____

Insured: GQ 6L

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

623M

Vehicle: IN / OUT

Date: _____ Person Contacted: L7988763

Veh No: F3T92867 Yr Regn: 29/06/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: R.A.P IONA AKA OAK Electric 4.0kw

Colour: Green / Blue A/C: Insured / Std / NI / NA

Sp. Reading: 2730 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SA1HDSGCONC000025

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Std / Rim / STD A/Rim or

Tyre Size: F: 110-90-12

R: AST

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. mm

D.O.A. 04/05/23

Survey held at

Rear

R/Bal. 2 mm

L/Bal. 2 mm

D.O.I. 12/6/23

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
ATTN: MOTOR CLAIMS DEPT

NO. : 43732

DATE : 10/06/2023
CLAIM NO. : 12208
POLICY NO. : V5004467

FROM : RAYMOND

VEHICLE NO. : FBT9286D
MAKE/MODEL : RAP / IONA AKA OAK

*not Arthur
his
12/6/23
P/P
2 day
can pho him 12/6/23*

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766	Supply/Install	2.00	\$60.00	120.00 ✓
2	SPRAY PAINT FRONT COWLING	Spray	1.00	\$185.00	185.00 ✓
3	SPRAY PAINT FRONT MUDGUARD	Spray	1.00	\$70.00	70.00 ✓
4	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837	Supply/Install	2.00	\$80.00	17 160.00 X
SUB TOTAL					\$535.00
GST @ 8 %					\$42.80
GRAND TOTAL (SGD)					\$577.80

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

*43732 *

bizSAFE



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	623M
Vehicle Details	
Vehicle No.:	FBT9286D
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2023
Vehicle Make:	R.A.P.
Vehicle Model:	IONA AKA OAK
Primary Colour:	Blue
Manufacturing Year:	2022
Engine No.:	-
Chassis No.:	SA1HDSGC0NC000025
Maximum Power Output:	-
Open Market Value:	\$4,136.00
Original Registration Date:	29 Jun 2022
First Registration Date:	29 Jun 2022
Transfer Count:	1
Actual ARF Paid:	\$621.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2032
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$9,689.00
COE Rebate Amount:	\$8,763.00
Total Rebate Amount:	\$8,763.00

The information contained herein is correct as at 12 Jun 2023

OK

Vehicle Details

Vehicle No.	Make / Model
FBT9286D	R.A.P. / IONA AKA OAK
Vehicle Type :	Vehicle Attachment 1 :
P01 - Passenger Scooter	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	SA1HDSGC0NC000025
Propellant :	Engine No. :
Electric	-
Motor No. :	Engine Capacity :
501203210900166	-
Power Rating :	Maximum Power Output :
4.0 kW	-
Maximum Laden Weight :	Unladen Weight :
380 kg	213 kg
Year Of Manufacture :	Original Registration Date :
2022	29 Jun 2022
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$9,689.00	28 Jun 2032
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
28 Jun 2023	-
Inspection Due Date :	Intended Transfer Date :
28 Jun 2025	12 Jun 2023
CO2 Emission :	CEV/VES Rebate Utilised Amount :