



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23005960/Kvy3m4 Date: 07/07/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMY 7739X	Veh. Inspected	SLJ 5849R
Policy No.		Coverage (\$)	0.00
Claim No.	C10022791 /SR	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	12/06/2023
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31218380	Colour	METALLIC GREY
Odometer	159735 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R16	FIRENZA	2 mm
L/H Front Tyre	215/60R16	FIRENZA	2 mm
R/H Rear Tyre	215/60R16	FIRENZA	5 mm
L/H Rear Tyre	215/60R16	FIRENZA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/06/2023	Inspection Date	12/06/2023
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	